

OIL CONSERVATION DIVISION

RICT I  
Box 1980, Hobbs NM 88241-1980

2040 Pacheco St.  
Santa Fe, NM 87505

RICT II  
Drawer DD, Artesia, NM 88210

RICT III  
000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. <b>30-025-33691</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Willowpeg State</b>
8. Well No. <b>1</b>
9. Pool name or Wildcat <b>North Vacuum; Atoka</b>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator <b>Marathon Oil Company</b>	
3. Address of Operator <b>P.O. Box 2409 Hobbs, NM 88240</b>	
4. Well Location Unit Letter <b>F</b> : <b>1980</b> Feet From The <b>North</b> Line and <b>1980</b> Feet From The <b>West</b> Line Section <b>35</b> Township <b>16-S</b> Range <b>34-E</b> NMPM <b>Lea</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>GL 4057' KB 4076'</b>	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **Replace Tubing / Acidize** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/26/99 MIRU pulling unit. ND wellhead. NU BOP. Set tbg stop w/plug at 10,372'. POOH. RIH perf 10,352' w/4 holes. Swab. Rel on/off tool at 12,362'. Rel pkr at 12,364'. POOH w/2 7/8" tbg and pkr. SIH w/pkr on 2 3/8" tbg (hydrotesting). Set pkr at 12,368'. Pickle tbg w/500 gals 15% acid. Flush w/45 bbls 2% KCL wtr. ND BOP. NU wellhead.  
1/30 Swab. RIH, rel plug at 12,362'. Acidize 12,463-476' w/2000 gals acid w/a 50% CO2 phase. Flush w/15 tons CO2. Flow well. Shut well in for build-up.  
2/3 Swab. Hook well up to facilities. RD pulling unit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 2/10/99  
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: