

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33763
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Rand Paulson Oil Company, Inc.
3. Address of Operator 508 W. Wall Suite 100 Midland, Texas 79701	8. Well No. 1
4. Well Location Unit Letter <u>R</u> : <u>1980</u> Feet From The <u>EAST</u> Line and <u>1980</u> Feet From The <u>South</u> Line Section <u>6</u> Township <u>16-S</u> Range <u>35-E</u> NMPM Lea County	9. Pool name or Wildcat Wildcat

7. Lease Name or Unit Agreement Name A.J. #6

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4055' GR
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: ATTEMPT TO CUT WINDOW & SIDETRACK <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-07-97 MIRU WORKOVER UNIT. DO CIBP @ 11,355'. SET CIBP @ 12,381'. SET WHIPSTOCK & CUT WINDOW IN 5 1/2" @ 12,375'. UNABLE TO ORIENT TOOL. SET CIBP 12,342'. CUT WINDOW ABOVE WHIPSTOCK @ 12,339'. UNABLE TO ORIENT TOOLS. ATTEMPT TO PLACE CEMENT BEHIND CASING 3 TIMES. NO FILL BEHIND CASING. CANNOT ORIENT TOOL PROPERLY. P.O.H. RELEASE UNIT.

PLAN TO MI DRILLING RIG. CUT 5 1/2" @ 9400'. PULL 5 1/2". DRILL TO 12400'. SET 5 1/2" CASING. DRILL HORIZONTALLY EAST & SOUTH.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE AGENT DATE 9-8-97
TYPE OR PRINT NAME O. H. ROUTH TELEPHONE NO. 915 687-0323

(This space for State Use)

APPROVED BY [Signature] TITLE Geologist DATE OCT - 3 1997
CONDITIONS OF APPROVAL, IF ANY: