| DETECT: DS & 50 Hoads, Not H210 OIL CONSERVATION DIVISION P.O. Box 2088 WELL AFI NO 30-025-33781 DETECT: DO Down DD, Aceak, NM H210 Santa Pe, New Maxico 87504-2088 30-025-33781 DO Down DD, Aceak, NM H210 Santa Pe, New Maxico 87504-2088 1 hadres Type of Law Status Pe, New Maxico 87504-2088 DO DOT USE TOB FOOM FOO PROFESSALS TO DOML CR TO DEPEN OR PLUG BACK TOA DEPENT DEFENT DESERVACION USE PAPELONIC NO REPENT OF PLUG BACK TOA DEPENT DEFENT ON USE NO. DOWL CR TO DEPEN OR PLUG BACK TOA DEPENT DESERVACION USE PAPELONIC NO REPENT OF PLUG BACK TOA DEPENT DESERVACION USE PAPELONIC NO REPENT OF PLUG BACK TOA DEPENT DESERVACION USE PAPELONIC NO REPENT (COM G-10) FOR BUCH PROFOSALS TO DOWL CR TO DEPEN OR PLUG BACK TOA DEPENT DESERVACION USE PAPELONIC NO REPENT (COM G-10) FOR BUCH PROFOSALS TO DOWL CR TO REPENT (COM G-10) FOR BUCH PROFOSALS TO MULLIS USE SOUTH (ch St., Artesia, NM 88210 1. Law Nom or Ubit Agesense Nome VAILS DEFENT Actesia O O DEPENT 10 South (ch St., Artesia, NM 88210 Not Indiana Crayburg San Andres Use Item South St. Artesia O DEPENT (Com CR PULL ARK REAR (R, R)) 1. Law Nom or Ubit Agesense Nome VaIL CRIME South St. Artesia O DEPENT (Com CREWED NORK) Item CREWED NORK) ALTENING CASING 1. Law Nom or Ubit Agesense (Compent Crayburg San Andres) 10 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REPORT REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Item CREPORT OF: REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Item CREPORT OF: R | iubnii 3 Copies 0 Appropriats District Office | State of New M Energy, minerals and Natural | | Form C-103 Revised 1-1-89 |
|--|--|--|--|---|
| DBTEXTLI Santa Fe, New Mexico 87504-2088 3/3/2/2/5/3/101 DBTMETLI Sinta Fe, New Mexico 87504-2088 5. Indicate Try of Later Try | DISTRICT I | P.O. Box 2088 | | 1 |
| DBTRUCH Graduational State | DISTRICT II | | | 5. Indicate Type of Lease |
| 100 Rb Baras MJ, Attec, NM 7410 Sub DNDRY NOTICES AND REPORTS ON WELLS (DO NOT USET INS FORM FOR POPCAMS TO DOBLL OR TO DEFERING PULG BACK TOA DIFFERENT RESERVOR. USE 'MPULCATION FOR PERMIT (PORM CONTROLLED NOT CONTROLLED TO DEFENSION FOR PERMIT (PORM CONTROLLED NOT CONTROLLED NOT PERMIT (PORM CONTROLLED NOT CONTROLLED NOT PERMIT (PORM CONTROLLED NOT CONTROLLED NOT CONTROLLED NOT PERMIT (PORM CONTROLLED NOT CONTROLLED NOT CONTROLLED NOT PERMIT (PORM CONTROLLED NOT CONTROLLED NOT PERMIT (PORM CONTROLLED NOT CONTROLLED NOT CONTROLLED NOT PERMIT (PORM CONTROLLED NOT CONTROLLED N | | | STATE X FEE | |
| SUMINE NOTICES AND REPORTS ON WELLS (DO NOT USE THE PORT MECHAND AND REPORTS OF PULL BACK TO A DIFFERENT RESERVOR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROCEASS) 1 Type of Wilk: | 000 Rio Brazos Rd., Aziec, NM 87410 | | | |
| Using Signed Operator Nichols A00 State 2. Nume of Operator 4. Well No. 1 3. Address of Operator 9. Pool same or Wildest 105. South 4th St., Artesia, NM 86210 9. Pool same or Wildest 4. Well Loades 9. Pool same or Wildest Unal Later N : 330 Foot Prom The South 10. South 4th St., Artesia, NM 86210 Sectors 5 Toronda Different South 10. Breathing South 10. Breating (Stow whether OP, RKS, R, GK, dt.) 4219' CR 11. Breating (Stow whether OP, RKS, R, GK, dt.) 4219' CR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SubSEQUENT REPORT OF: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Alterning GASING CHANGE PLANS COMER: Pull RBP X 12. Deckide Prograd Operation (Clearly state all princes deall, and fire period data, building data of pump. Unset tubing anchor. Nippled up BOP. TOOH with tubing. Shut down for night. 8-6-97 - Moved in and rigged up pulling unit. TOH with rots and pump. Unset tubing anchor. Nippled up BOP. TOOH with tubing. Cavens tool, seating nipple, 28 joints of 2-7/8" tubing. Set tubing anchor. Nippled up OPON Took with tubing anchor. Nippled up Comercian data for state of any taxing and tragged out pump. Returned to production. Prodel with tubing anchor and 126 | (DO NOT USE THIS FORM FOR PF DIFFERENT RESE | ROPOSALS TO DRILL OR TO DEEPE ERVOIR. USE "APPLICATION FOR F | EN OR PLUG BACK TO A | |
| YATES PETROLEUM CORPORATION 1 Addeed of Operator 9. Pod same or Wildset 103 South 4th St., Artesia, NM 88210 9. Pod same or Wildset Wall Loadio 9. Pod same or Wildset Usid Latter M.; 330 Feet From The South 103 South 4th St., Artesia, NM 88210 11 are set 370 Feet From The West 4 Wall Loadio 10. Exercise (Skow whither DP, RKB, RT, GR, set) New Set Lea County 10. Exercise (Skow whither DP, RKB, RT, GR, set) 12. Exercise (Skow whither DP, RKB, RT, GR, set) Notice OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON GR ALTERING CASING ALTERING CASING PLUG AND ABANDON PULL OR ALTER CASING Change PLANS County Of REPORT OF: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING POLL OR ALTER CASING County Of REPORT ARE PLANS County Of REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING POLL OR ALTER CASING County Of REPORT OF: REMEDIAL WORK ALTERING CASING POLL OR ALTER CASING County Of REPORT OF: | |] 011428 | | Nichols AQO State |
| 1 Addate of Operator 9. Pod same or Wildca 105 South 4th St., Artesia, NM 88210 Maljamar Grayburg San Andres 4 Will Losido Usik Letter M : 330 Fort From The South Lias and 370 Fort From The West Lias 105 South 4th St., Artesia, NM 88210 100 Fort From The South South Maljamar Grayburg San Andres 4 Will Losido Usik Letter M : 330 Fort From The South 100 Fort Fort The West Lias 10 Lieving Class 175 Range 33E NMPM Lea County 11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRULING OPNS. PLUG AND ABANDONMENT DULL OR ALTER CASING CHANGE PLANS COMMENCE DRULING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB DULL OR ALTER CASING CHANGE PLANS OTHER Pull RBP K 10 Scended Operation (Clash state all permised statid, and five perisent state, ischular statid atter d starting any proposed South Omegan and tagged RBP 11 Decide Up BOP. TOOM with tubing. TOOH with robing and baller. THE tubing. Set tubing and haller the diage and balled stand and tagged RBP. 12 OPH with tubing anchor and 126 joints of 2- | | ወ ለጥ ቸ በ N | | |
| 105 South 4th St., Artesia, NM 88210 Maljamar Grayburg San Andres 4 Wall Later M.: 330 Fee From The South Lias and 370 Fee From The West Line 106 South 118 south 107 Fee From The South South Lias and 370 Fee From The West Line 107 State 10 Evening INSer which: DF RKB, RT, GR, atc.) MMPM Lea Compare 10. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK AltERING CASING PLUG AND ABANDON OTHER: | | | | 9. Pool name or Wildcat |
| Unit Letter M 330 Feet From The South Lise and 370 Feet From The West Lise Secke 5 Township 175 Range 33E NMPM Lea Comp 10 Elevation (3kow whether DF RKB, RT, GR, etc.) 4219' GR Gradien (2000) Gradien (2000) Gradien (2000) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON Gradien (2000) Gradien (2000) Gradien (2000) PULO RAITER CASING Gradien (2000) CHANGE PLANS Gradien (2000) Gradien (2000) DULLOR ALTER CASING Gradien (2000) Gradien (2000) Gradien (2000) Gradien (2000) DIFER: Gradien (2000) GRADIEN (2000) Gradien (2000) Gradien (2000) Gradien (2000) DULLOR ALTER CASING Gradien (2000) Gradien (2000) Gradien (2000) Gradien (2000) Gradien (2000) DIFER: Gradien (2000) Gradien (2000) Gradien (2000) Gradien (2000) Gradien (2000) DIFER: Gradien (2000) | 105 South 4th St., Ar | tesia, NM 88210 | | |
| Sector 5 Township 17S Rage 33E NMPM Lea County 10. How Market M. P. RKB, RT, GR, etc.) 4219' GR 4219' GR 4219' GR 4219' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Alterning CASING DEEMPORABLY ABANDON CHANGE PLANS COMMENCE DFULING OPNS. PLUG AND ABANDONMENT DULL OR ALTER CASING CASING TEST AND CEMENT ADB CASING TEST AND CEMENT ADB D'UL OR ALTER CASING COMMENCE DFULING OPNS. PLUG AND ABANDONMENT D'UL OR ALTER CASING CASING TEST AND CEMENT ADB COMMENCE DFULING OPNS. PLUG AND ABANDONMENT D'UL OR ALTER CASING COMMENCE DFULING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT ADB D'UL OR ALTER CASING COMMENCE DFULING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT ADB D'UL OR ALTER CASING Comments and rigged up pulling unit. TOOH with rubing and side proved and bailed and pump. Unset tubing anchor. 12. Decedee out public grant and TIH. Tagged sand. Bailed sand and tagged RBP. at 4460'. | | 30 South | | n n - West |
| 10. Elevation (Show which DP, RKB, RT, GR, etc.) 4219' GR n. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT XOB OTHER: VUL OR ALTER CASING CASING TEST AND CEMENT XOB OTHER: OTHER: PUIL RBP E VIL OR ALTER CASING CASING TEST AND CEMENT XOB OTHER: OTHER: PUIL RBP E VIL OR ALTER CASING CASING TEST AND CEMENT XOB OTHER: OTHER: 10. Decide Proposed or Complete Operational (Clearly rate all perineral data) including cainated data of staring any proposed wordy SEE RULE 103. See RULE 103. 8-6-97 - Moved in and rigged up pulling unit. TOOH with tubing and bailer. THE with tubing and bail | Unit Letter: | 50 Feet From The | Line and70 | Feet From The WESC Line |
| 4219' GR N. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PEMPORABILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DITHER: OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DITHER: OTHER: Pull RBP X 12. Newide propector Completed Operations (Clearly sate all periment details, and give periment dates, including estimated date of starting any proposed X 8-6-97 Moved in and rigged up pulling unit. TOOH with rods and pump. Unset tubing anchor: 8-6-97 Ploted up bDID dog bailer and TIH. Tagged sand. Bailed sand and tagged RBP at 4460'. 8-7-97 Ploted up bDID dog bailer. TIH with retrieving head and latched onto RBP. TOOH with tubing and RBP. Solits 52-3/8" tubing, Cavens tool, seating nipple, 28 joints of 2-7/8" tubing, tubing anchor. 8-8-97 THH with pump and rods. Spaced out pump. Returned to production. Producing perforations: 4130-4334' | Section 5 | Township 17S | | NMPM Lea County |
| II. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING FEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB DTHER: OTHER: Pull RBP K CASING TEST AND CEMENT JOB K DTHER: OTHER: Pull RBP K K K VALUER ALTER CASING OTHER: Pull RBP K K DTHER: OTHER: Pull RBP K K 12. Pacenda Proposed or Completed Operational dividity state all pertinent dividity, and give periment dividity and the of starting any proposed Work) SEE KULE 1003. 8-6-97 - Moved in and rigged up pulling unit. TOOH with rods and pump. Unset tubing anchor. Nippled up BOP. TOOH with tubing. Shut down for night. BP. 8-7-97 - Picked up bulldog baller and TH. Tagged sand. Bailed sand and tagged RBP. 8-8-97 - TH with 5 joints 2-3/8" tubing, Cavens tool, seating nipple, 28 joints of 2-7/8" tubing, tubing anchor and 126 joints of 2-7/8" tubing. Set tubing anchor. Nippled down BOP. THH with pump and rods. Spaced out pump. Returned to production. | | (/////// | | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: DILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: PULL OR ALTER CASING K OTHER: OTHER: PULL OR ALTER CASING K PULL OR ALTER CASING OTHER: PULL OR ALTER CASING FLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: PULL OR ALTER CASING FLUG AND ABANDONMENT DTHER: OTHER: PULL OR ALTER CASING MADE ADDR CASING TEST AND CEMENT JOB DTHER: OTHER: PULL OR ALTER CASING MADE ADDR CASING TEST AND CEMENT JOB DTHER: DIL OR ALTER CASING OTHER: PULL OR ALTER CASING MADE ADDR DTHER: PULL OR ALTER CASING OTHER: PULL ADDR MADE ADDR DTHE ADDR DOTH of the UP ADDR DOTH ADDR TOOH WITH TUB ADDR MADE ADDR | | | | anort or Other Date |
| PEFFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING COMMENCE DRILLING OPNS. COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PTHER: Pull Not Change depriment deally state all periment deally and file state. Comment deally state all periment deally state. Comment deally state. Comment deally state. Both COM WITH tubing and bailer. | | | | - |
| TEMPORABILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB DTHER: OTHER. Pull RBP CASING TEST AND CEMENT JOB Commencement Job 12. Describe Proposed or Complete Operations (Clearly state all performed descriptions) date, including estimated date of starting any proposed work) SEE RULE 103. See 97 - Moved in and rigged up pulling unit. TOOH with rods and pump. Unset tubing anchor. Nippled up BOP. TOOH with tubing. Shut down for night. 8-6-97 - Picked up bulldog bailer and TIH. Tagged sand. Bailed sand and tagged RBP at 4460'. POOH with tubing and bailer. TOOH with tubing and RBP. 8-8-97 - TIH with 5 joints 2-3/8" tubing, Cavens tool, seating nipple, 28 joints of 2-7/8" tubing, tubing anchor and 126 joints of 2-7/8" tubing. Set tubing anchor. Nipple down BOP. TIH with pump and rods. Spaced out pump. Returned to production. Producing perforations: 4130-4334' (Grayburg) and 4488-4714' (San Andres). Iberety cently us bis information boors as fusced complete to the best of my translege mabbelled. THE Sept. 24, 1993 Type carent name Rusty Klein THE Sept. 24, 1993 The call of state Use) Orig. Signed by Paul Kautz DATE OCT 07 1997 Ceologist THE <td>È</td> <td>(</td> <td>n </td> <td>(~~) (*~</td> | È | (| n | (~~) (*~ |
| DULL OR ALTER CASING CASING TEST AND CEMENT JOB DTHER: OTHER: Pull RBP ID DECIDE Proposed or Completed Operations (Clearly state all pertines) duals, and give periment duits, including estimated duits of starting any proposed Work) SEB RULE 103. Se-6-97 - Moved in and rigged up pulling unit. TOOH with rods and pump. Unset tubing anchor. Nippled up BOP. TOOH with tubing. Shut down for night. 8-6-97 - Picked up bulldog bailer and TIH. Tagged sand. Bailed sand and tagged RBP at 4460'. POOH with tubing and Bailer. TIH with retrieving head and latched onto RBP. TOOH with tubing and RBP. 8-8-97 - TIH with 5 joints 2-3/8" tubing, Cavens tool, seating nipple, 28 joints of 2-7/8" tubing, tubing anchor and 126 joints of 2-7/8" tubing. Set tubing anchor. Nippled down BOP. TIH with pump and rods. Spaced out pump. Returned to production. Producing perforations: 4130-4334' (Grayburg) and 4488-4714' (San Andres). Iberdy cettly the information books to any knowledge and belled. stowners THE OF PROTENTAME RusEy Klein THE OPERATIONS Technician Orig. Signed by Paul Kautz Orig. Signed by Paul Kautz Year OR PROTENTAME Orig. Signed by Paul Kautz Year OR PROTENTAME Orig. Signed by Paul Kautz | | PLUG AND ABANDON | AEMEDIAL WORK | ALTERING CASING |
| DTHER: OTHER: Pull RBP K 12. Describe Proposed or Completed Operations (Clearly state all perimens data), and give perimens data; including estimated data of starting any proposed work) SEE RULE 1103. 8-6-97 - Moved in and rigged up pulling unit. TOOH with rods and pump. Unset tubing anchor. Nippled up BOP. TOOH with tubing. Shut down for night. 8-7-97 - Picked up bulldog bailer and TIH. Tagged sand. Bailed sand and tagged RBP at 4460'. POOH with tubing and bailer. TIH with retrieving head and latched onto RBP. TOOH with tubing anchor and 126 joints of 2-7/8" tubing. Set tubing anchor. Nippled down BOP. TIH with pump and rods. Spaced out pump. Returned to production. Producing perforations: 4130-4334' (Grayburg) and 4488-4714' (San Andres). I hereby certify the information shows is the and complete to the best of my throwickings and belief. I hereby certify the information shows is the and complete to the best of my throwickings and belief. I hereby certify the information shows is the and complete to the best of my throwickings and belief. I hereby certify the information shows is the and complete to the best of my throwickings and belief. I hereby certify the information shows is the and complete to the best of my throwickings and belief. I hereby certify the information shows is the and complete to the best of my throwickings and belief. I hereby certify the information shows is the and complete to the best of my throwickings and belief. I hereby certify the information shows is the and complete to the best of my throwickings and belief. | EMPORARILY ABANDON | CHANGE PLANS | | G OPNS. |
| 12. Detrike Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 103. 8-6-97 - Moved in and rigged up pulling unit. TOOH with rods and pump. Unset tubing anchor. Nippled up BOP. TOOH with tubing. Shut down for night. 8-7-97 - Ficked up bulldog bailer and TH. Tagged sand. Bailed sand and tagged RBP at 4460'. POOH with tubing and bailer. THH with retrieving head and latched onto RBP. TOOH with tubing and RBP. 8-8-97 - TH with 5 joints 2-3/8" tubing, Cavens tool, seating nipple, 28 joints of 2-7/8" tubing, tubing anchor and 126 joints of 2-7/8" tubing. Set tubing anchor. Nippled down BOP. THH with pump and rods. Spaced out pump. Returned to production. Producing perforations: 4130-4334' (Grayburg) and 4488-4714' (San Andres). I herdy certify the public starts and complete to the best of my knowledge and belief. NONATURE Mathematic shows a the sed complete to the best of my knowledge and belief. NONATURE Mathematic shows a the sed complete to the best of my knowledge and belief. TORE OF FRONT NAME Orig. Signed by Paul Kautz Geologist. Pressor for State Use) Orig. Signed by Paul Kautz Geologist. | ULL OR ALTER CASING | | CASING TEST AND C | |
| 12. Describe Proposed of Completed Operations (Clearly state all periment data), and give periment datas, including estimated data of starting any proposed works SEE RULE 1103. 8-6-97 - Moved in and rigged up pulling unit. TOOH with rods and pump. Unset tubing anchor. Nippled up BOP. TOOH with tubing. Shut down for night. 8-7-97 - Picked up bulldog bailer and TIH. Tagged sand. Bailed sand and tagged RBP at 4460'. POOH with tubing and bailer. TIH with retrieving head and latched onto RBP. TOOH with tubing and RBP. 8-8-97 - TIH with 5 joints 2-3/8" tubing, Cavens tool, seating nipple, 28 joints of 2-7/8" tubing, tubing anchor and 126 joints of 2-7/8" tubing. Set tubing anchor. Nippled down BOP. TIH with pump and rods. Spaced out pump. Returned to production. Producing perforations: 4130-4334' (Grayburg) and 4488-4714' (San Andres). Iberdy cattly tub tub information throws to the best of my throwidge and belief. Hondrom Tubase for State Use) Orig. Signed by Paul Kautz Geologist. THE DATE OCT 07 2597 | THER | [| OTHER: Pull RB | P |
| SIGNATURE Operations Technician DATE Sept. 24, 1997 TYPE OR PRINT NAME Rusty Klein TYPE OR PRINT NAME Rusty Klein THE Operations Technician TYPE OR PRINT NAME Operations Technician TYPE OR PRINT NAME Orig. Signed by Paul Kautz Geologist TILE | work) SEE RULE 1103. 8-6-97 - Moved in an anchor. Nippled up 8-7-97 - Picked up h | nd rigged up pulling ų BOP. TOOH with tubin bulldog bailer and TIH h tubing and bailer. | nit. TOOH with g. Shut down fo . Tagged sand. | rods and pump. Unset tubing r night. Bailed sand and tagged RBP |
| SIONATURE AFTROVED BY Creations Technician DATE Sept. 24, 1997 TYPE OR PRINT NAME Rusty Klein Telephone No. 505/748-1 (This space for State Use) Orig. Signed by Paul Kautz Geologist TILE DATE OCT 07 1997 | TOOH with tubing and 8-8-97 - TIH with 5 2-7/8" tubing, tubin down BOP. TIH with | joints 2-3/8" tubing, ng anchor and 126 join pump and rods. Space | Cavens tool, se ts of 2-7/8" tub d out pump. Ret | ating nipple, 28 joints of ing. Set tubing anchor. Nipple urned to production. |
| TYPE OR PRINT NAME Rusty Klein TYPE OR PRINT NAME (This space for State Use) Orig. Signed by Paul Kautz APPROVED BY OCT 07 1997 | TOOH with tubing and 8-8-97 - TIH with 5 2-7/8" tubing, tubin down BOP. TIH with Producing perforatio | joints 2-3/8" tubing, ng anchor and 126 join pump and rods. Space ons: 4130-4334' (Gray | Cavens tool, se its of 2-7/8" tub d out pump. Ret burg) and 4488-4 | ating nipple, 28 joints of ing. Set tubing anchor. Nipple urned to production. |
| (This space for State Use) Orig. Signed by Paul Kautz APTROVED BY DATE | TOOH with tubing and 8-8-97 - TIH with 5 2-7/8" tubing, tubin down BOP. TIH with Producing perforation Hereby certify that this information above in | joints 2-3/8" tubing, ng anchor and 126 join pump and rods. Space ons: 4130-4334' (Gray | Cavens tool, se its of 2-7/8" tub d out pump. Ret burg) and 4488-4 | ating nipple, 28 joints of ing. Set tubing anchor. Nipple urned to production. 714' (San Andres). |
| Paul Kautz Geologist TILE DATE OCT 07 1997 | TOOH with tubing and 8-8-97 - TIH with 5 2-7/8" tubing, tubin down BOP. TIH with Producing perforation Hereby certify that the information above in HONATURE | joints 2-3/8" tubing, ng anchor and 126 join pump and rods. Space ons: 4130-4334' (Gray | Cavens tool, se its of 2-7/8" tub d out pump. Ret burg) and 4488-4 | ating nipple, 28 joints of ing. Set tubing anchor. Nipple urned to production. 714' (San Andres). Fechnician <u>Sept. 24, 1997</u> |
| Paul Kautz Geologist mile DATE DATE | TOOH with tubing and 8-8-97 - TIH with 5 2-7/8" tubing, tubin down BOP. TIH with Producing perforation Hereby certify that the information above in SHONATURE | joints 2-3/8" tubing, ng anchor and 126 join pump and rods. Space ons: 4130-4334' (Gray | Cavens tool, se its of 2-7/8" tub d out pump. Ret burg) and 4488-4 | ating nipple, 28 joints of ing. Set tubing anchor. Nipple urned to production. 714' (San Andres). Fechnician <u>Sept. 24, 199</u> 7 |
| | TOOH with tubing and 8-8-97 - TIH with 5 2-7/8" tubing, tubin down BOP. TIH with Producing perforation Producing perforation i hereby certify that the information above is stonatures TYPE OR PRDITNAME Rusty Kle | joints 2-3/8" tubing, ng anchor and 126 join pump and rods. Space ons: 4130-4334' (Gray | Cavens tool, se its of 2-7/8" tub d out pump. Ret burg) and 4488-4 | ating nipple, 28 joints of ing. Set tubing anchor. Nipple urned to production. 714' (San Andres). Fechnician <u>Sept. 24, 1997</u> |
| CONDITIONS OF AFFROATS, IF ANY: | TOOH with tubing and 8-8-97 - TIH with 5 2-7/8" tubing, tubin down BOP. TIH with Producing perforation Producing perforation i hereby certify that the information above is stonatures TYPE OR PRDITNAME Rusty Kle | joints 2-3/8" tubing, ng anchor and 126 join pump and rods. Space ons: 4130-4334' (Gray fue and complete to the best of my knowledge fue in Prig. Signed by Paul Kautz | Cavens tool, se its of 2-7/8" tub d out pump. Ret burg) and 4488-4 | ating nipple, 28 joints of ing. Set tubing anchor. Nipple urned to production. 714' (San Andres). Fechnician DATE Sept. 24, 1997 TELEPHONE NO. 505/748-1 |
| | TOOH with tubing and 8-8-97 - TIH with 5 2-7/8" tubing, tubin down BOP. TIH with Producing perforation i hereby certify that this information above is stonatures TYPE OR PRINT NAME (This space for Siste Use) | joints 2-3/8" tubing, ng anchor and 126 join pump and rods. Space ons: 4130-4334' (Gray nucleased complete to the best of my knowledge fun | Cavens tool, se its of 2-7/8" tub id out pump. Ret burg) and 4488-4 mathematic mathematic | ating nipple, 28 joints of ing. Set tubing anchor. Nipple urned to production. 714' (San Andres). Fechnician DATE Sept. 24, 1997 TELEPHONE NO. 505/748-1 |