

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33931
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	VA-605
7. Lease Name or Unit Agreement Name	Brunson AQK State Com
8. Well No.	1
9. Pool name or Wildcat	Wildcat Atoka

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>G</u> : <u>2260</u> Feet From The <u>North</u> Line and <u>1795</u> Feet From The <u>East</u> Line Section <u>10</u> Township <u>16S</u> Range <u>35E</u> NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4003' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Frac perforations ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-17-98 - Swab & flow test. Shut well in.
4-18-98 - Swab and flow test. Shut well in.
4-20-98 - Prep to frac.
4-21-98 - Rigged up treesaver. Frac'd perforations 11702-11734' (via 2-7/8" tubing) with 36000 gallons 40# CMHPG, 25% methanol binary 70-60Q foam and 40000# 20-40 interprop. Rigged down treesaver. Shut well in for 3 hours. Opened well up and began flowing back frac.
4-22-98 - Flowing frac back. Shut well in.
4-23-98 - Bled well down. Pumped 70 bbls 3% KCL down tubing. Did not load. Released packer. Nipped down tree and nipped up BOP. TOOH with packer. TIH with retrieving tool and tagged sand at 11815'. Washed down to RBP at 11900'. Circulate clean. Released RBP. Hanging up. Pulled up 25' and hung up. Worked back down - would not come up. Pulling 130000#. Picked up 3 joints tubing. Worked up and down - RBPM came loose. TOOH. TIH with 5-1/2" 10K Uni VI packer with 1.875" on/off tool on 357 joints. Nipped down

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE April 27, 1998
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

CHIEF OF DIVISION
SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

YATES PETROLEUM CORPORATION
Brunson AQK State Com #1
Section 10-T16S-R35E
Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

BOP. Nippled up tree. Set packer. Tested annulus to 1000 psi. Swabbing.
4-24-98 - Swab and flow test. Shut well in.
4-25-98 - Released well to production department.



Rusty Klein
Operations Technician
April 27, 1998