

DISTRICT I

P. O. Box 1980, Hobbs, NM 88240

DISTRICT II

P. O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 87504-2088

WELL API NO.

30-025-34064

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Maljamar Grayburg San Andres

1. Type of Well:

OIL ☒ GAS ☐
WELL ☒ WELL ☐ OTHER

2. Name of Operator

The Wiser Oil Company

8. Well No.

128

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797

9. Pool name or Wildcat

Maljamar Grayburg San Andres

4. Well Location

Unit Letter C : 660 Feet From The North Line and 1830 Feet From The West Line

Section 4 Township 17S Range 32E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4186' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Re-perf. & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/03/98 MIRU Pool Well Service. POH w/rods & pump. ND WH. NU BOP. Release TAC & POH w/2-7/8" tbg. RU Halliburton & perforate Grayburg f3895', 97', 3908', 29', 40', 41', 51', 52', 59', 60', 66', 78', 86', 88', 89', 90', 4024', 25', 26', 32', 33', 41', 48', 49', 51', 54', 55', 58' & 59' w/4 SPF. RIH w/AD-1 pkr. & 2-7/8" tbg. to 3840'.

11/04/98 Test tbg. to 4000#. Pressure csg. to 500#. Acidized Grayburg Vac. 3895'-4122' w/1000 gals. Toluene & 2500# rock salt. ATP 2900# @ 5.8 bpm. MTP 3700# @ 6.6 bpm. Max. Rate 7.0 bpm. ISIP 2900#. 5 min. 2300#. 10 min. 1870#. 15 min. 1650#. 1 hr. Vac. Release pkr. POH w/pkr. & tbg. RIH w/2-7/8" tbg. & TAC. Set TAC w/12,000# tension. Tbg. @ 4171'. SN @ 4137'. TAC @ 3882'. ND BOP. NU WH. RIH w/rods & 2-1/2" x 1-3/4" x 16' RHTC pump. Left well pumping to MGBU Battery.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE October 18, 2001

TYPE OR PRINT NAME Mary Jo Turner

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE NOV 19 2001