

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88241-1980

DISTRICT II  
811 S. First Street, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 South Pacheco  
Santa Fe, New Mexico 87505

WELL API NO. 30-025-34085
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-0684
7. Lease Name or Unit Agreement Name HANNAH STATE
8. Well No. 1
9. Pool Name or Symbol KEMNITZ MORROW

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
Name of Operator ELK OIL COMPANY	
3. Address of Operator POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310	
4. Well Location Unit Letter <u>B</u> <u>660</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>24</u> Township <u>16 SOUTH</u> Range <u>34 EAST</u> NMPM <u>LEA</u> County 10. Elevation (Show whether DE, RKB, RT, GR, etc.) 4051' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING CPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  
SEE RULE 1103

ON 10/16/97 PLUGGED AND ABANDONED WELL AS FOLLOWS:

SPOT 40 SXS ON BOTTOM.  
SPOT 40 SXS AT 11,111'.  
SPOT 40 SXS AT 10,186'.  
SPOT 40 SXS AT 8,051'.  
SPOT 40 SXS AT 6,140'.  
SPOT 55 SXS AT 4,092'. 50 IN / 50 OUT @ 5/8" SHOE.  
SPOT 55 SXS AT 1,748'.  
SPOT 55 SXS AT 420'. 50 IN / 50 OUT.  
SPOT 10 SXS AT SURFACE.

INSTALL DRY HOLE MARKER. CIRCULATE HOLE WITH 10# MUD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRESIDENT DATE 3/11/98  
TYPE OR PRINT NAME JOSEPH J. KELLY TELEPHONE NO. 505-623-3190

Use space for State Use  
APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JUN 13 1998  
REASON OF APPROVAL (IF ANY):

DD