Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I			
P.O. Box 1980, Hobbs NM 88241-1980	OIL CONSERVAT		WELL API NO.
DISTRICT II	Santa Fe, N		30-025-34284
P.O. Drawer DD, Artesia, NM 88210	Santa 10, 10	WI 07303	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOT	ICES AND REPORTS ON V	VELLS	22371 
(DO NOT USE THIS FORM FOR PRODIFFERENT RESER		PEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name  Honteith "C"
1. Type of Well: OIL GAS WELL [	OTHER		- Honce ton C
2. Name of Operator			8. Well No.
Bass Enterprises Production 3. Address of Operator			P. F. ame or Wildcat
P.O. Box 2760 Midland. TX	79702-2760		Lovington (Penn)
4. Well Location Unit Letter B: 660	Feet From The Nor	th Line and 180	30' Feet From The East Line
Section 13	Township 16S	Range 36E	NMPM Lea County
		7.9' RF 3874.2' KB	
11. Check Ap	propriate Box to Indic	ate Nature of Notice,	Report, or Other Data
NOTICE OF IN	ITENTION TO:	SUE	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONIMENT
PULL OR ALTER CASING		CASING TEST AND CE	EMENT JOB
OTHER:	[	OTHER: Intermedi	ate Casing
LT&C casing set at (0-34	69') 55 POZ C w/ additives.		5'). 82 joints 28# WC-50. C Neat. Circulated 98
sacks to surface. WOC 2 Drill cement, test casin	ng to 1000 psi. OK 5/11/	<b>'98.</b>	
sacks to surface. WOC 2	424 220		
Sacks to surface. WOC 2 Drill cement, test casin  Clutted P 969  I hereby certify that the information above is to	424 220	wledge and belief.	k date 7/8/98
Sacks to surface. WOC 2 Drill cement, test casin  Clutted P 969  I hereby certify that the information above is to	434 330 rue and complete to the best of my know Wulber	wledge and belief.	*K DATE <b>7/8/98</b> TELEPHONE NO. <b>(915)683-2277</b>
Sacks to surface. WOC 2 Drill cement, test casin  Clatified P 969 I hereby certify that the information above is to  SEGNATURE	434 330  Tue and complete to the best of my know  Wulber	wledge and belief.	
Sacks to surface. WOC 2 Drill cement, test casin  Clatified P 969  I hereby certify that the information above is to  SEGNATURE	The and complete to the best of my know  Wulber	wledge and belief.	TELEPHONE NO. (915)683-2277
Sacks to surface. WOC 2 Drill cement, test casin  Clatified P 969  I hereby certify that the information above is to  SAGNATURE	434 330  Tue and complete to the best of my know  Wulber	wledge and belief.	TELEPHONE NO. (915)683-2277