Difference OIL CONSERVATION DIVISION P.O. Box 2088 Difference P.O. Box 2088 Difference Santa Pe, New Mexico 87504-2088 Difference Santa Pe, New New Contanta New Control 10000 Nex 10000 New Control	State of New Mexico Energy, Minerals and Natural Resources Dep	artment Form C-103 Revised 1-1-89	
P.O. Box 2088 PO. Dox 2088 SINTETT Santa Fe, New Mexico 87504-2088 SUBSTITT Santa Fe, New Mexico 87504-2088 SUBSTITT Substitution CONTUNE TRANSMERTIN Substitution CONTUNE TRANSMERTIN Substitution CONTUNE TRANSMERTIN Substitution CONTUNE TRANSMERT RESERVOR, USE AND REPORTS ON WELLS			
SETIET D. O. Drawel D. Anada, NM #2110 Santa Fe, New Mexico #7504-2088 30-0-22-34498 SCID Drawel D. Anada, NM #2110 Santa Fe, New Mexico #7504-2088 30-0-22-34498 SCID Drawel D. Anada, NM #2110 Sub DR A. Anao, NM #7110 5. Indices Type of Less: 9. Sets DR A. Anao, NM #7110 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROFONCE, USE PROFORE NOR FLUE BACK TO A DUFFERENT RESERVCH. USE "APPLICATION FOR PERMIT: Prof Wall. 7. Less Nume of Use Agreement Nume Type of Wall Common Ruby ASV State Comf Type of Wall Omma Ruby ASV State Comf Type of Wall Omma Ruby ASV State Comf Type of Wall Advest of Operator 4. Well No. TATES PETROLEUM CORPORATION 4. Well No. 1 Advest of Operator 4. Well No. 1 Totage Totage Intermine The Control of Notice, Report, or Other Data NOTICE OF INTENTION TO: State RLB RUSANDON CHANGE PLANS Commence of Notice, Report, or Other Data NOTICE OF INTENTION TO: RFORM REMEMINE VARIANDON CHANGE PLANS COMMENCE DRILING OPNS. Plug AND ABANDON LI CALLER CASING CHANGE PLANS COMMENCE DRILING OPNS. Plug AND ABANDON Check Appropriate Box to Indicate Nature of N		ION WELL API NO.	
3. Lokasa (no action) 3. Lokasa (no action) 000000000000000000000000000000000000	Santa Fe, New Mexico, 87504-2081	30-025-34498	
V-4415 V-4415 V-4415 CONTRET ON THE PROPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPORALS TO OR FUNCT ON FOR PENATT DEFENST USE SERVICE NOT FOR PENATT PUT OF SUCH PROPORALS) Type of Wall Colspan="2">Colspan="2">Value of PROPORALS) Type of Wall Colspan="2">Colspan="2">Colspan="2">Colspan="2">Colspan="2">Value of Operator Operator Operator Operator Operator Operator Sector Sector Sector Sector Sector Sector NOTH Lise and TOD Sector Sector Sector Sector NOTH Lise and TOD Sector NOTH Lise and ToD <td< td=""><td></td><td>5. Indicate Type of Lesse</td></td<>		5. Indicate Type of Lesse	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TOA DEFERENT RESERVOR. USE APPLICATION FOR PERMAT (FORM C-101) FOR SUCH PROFOCALS) 1. Lase Nume of Usil Agreement Nume (FORM C-101) FOR SUCH PROFOCALS) Type of Wall: Well Composition 8. Well No. Nume of Openator 8. Well No. 1 Address of Openator 8. Well No. 1 DS South 4 ch St., Artesia, NM 88210 8. Well No. 1 Well Cocalies 15 Townab of Demator Wildsat Anderson Ranch Morrow (gr Socion 15 Townab of Demator Nilson of Wildsat Anderson Ranch Morrow (gr Socion 15 Townab of Demator Nilson of Notice, Report, or Other Data NOTICE OF INTENTION TO: Scolon 10 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: RPORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING LCA ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON PLUG AND ABANDON LCA ALTER CASING COMMENCE DETT JOB OTHER: Perforate Demator Job of			
Different reservoing. Use "APPLICATION FOR PERMAT" Type of Well: Gen	OTICES AND REPORTS ON WELLS		
Wall Wall Weil Name Ruby ASV State Comf Nume of Openator 4. Weil Na 1 Addres of Openator 9. Pool same or Wildowt 1 Addres of Openator 9. Pool same or Wildowt Anderson Ranch Morrow (g Weil Lesson 9. Pool same or Wildowt Anderson Ranch Morrow (g Weil Lesson 1 1650 Feet Prom The East Section 15 Township 165 Range 32E NMTM Mult Lesson 10 East 4304 ' GR 4304 ' GR 4304 ' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: RPGRARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING COMMENCE ADD COMENT JOB OTHER: Perforate Decrement of tubing each in and rigged up pulling unit. TH with 43/4" bit, scraper and 10 Joints of tubing. Shut down. Shut down. The with 43/4" bit, scraper and 10 Joints of tubing works and rigged down wireline. Shut down. The with 43/4" bit, scraper and 10 Joints of tubing worolks and rigged down wireline. Shut do	ESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name	
Name of Opensor 1 YATES PETROLEUM CORPORATION 1 Addem of Opensor 19. Pod amme of Wilcat 105 South 4th St., Artesia, NM 88210 9. Pod amme of Wilcat Well Location 10 Well Location 10 Well Location 10 Social 15 Tomaship 165 Social 10 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: FFORM REMEDIAL WORK PLUG AND ABANDON LOR ALTER CASING Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: FFORM REMEDIAL WORK PLUG AND ABANDON LOR ALTER CASING COMMENCE DRILLING OPNS. LOR ALTER CASING OTHER: Perforate Describe RULE 100. Cleaned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 500 12-30-98 - Cleaned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 500 12-31-98 - TIH with remainder of 2-7/8" tubing and tagged PBTD at 12480'. Nippled up BOP. Pickled tubing with 500 gallons of 15% HCL acid. Reversed acid out. Tested cas 12-30-99 -			
YATES PETROLEUM CORPORATION Address of Operator Do South 4th St., Artesia, NM 88210 Pool asses of Wilder Anderson Ranch Morrow (get and operator South 4th St., Artesia, NM 88210 Pool asses of Wilder Anderson Ranch Morrow (get and operator Weil Lessin H. : 1650 Fee Prom The North Lise and _700 Fee Prom The East Address of Wilder Anderson Ranch Morrow (get and the statistic operator is and the statis	CTHER		
Address of Operator 9. Pool masss or Wildest DOS South 4 th St., Artesia, NM 88210 9. Pool masss or Wildest Well Lossie H.: 1650 Feet Prom The North Line and 700 Feet Prom The East Socien 15 Township 1658 Rame 322 NMFM Lea 0 4304 / GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: FORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS OTHER: Perforate Describe Tropped or Completed Operations (Clearly state all perinent dealit, and give perinent deals, including estimated date of starting any proposed wery SEE RULE 1005. Subt down. 12-30-98 - Cleaned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 500 12-30-98 - Cleaned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 500 tubing and ranged perinent dealit, and give perinent deate of starting any proposed 02 2000/ 0.K. TOOR. Rigged up wireline. TIH with 4-3/4" bit, scraper and 10 points of tubing. Shut down.	PORATION		
Well Lossion			
Unit Later H : 1650 Feet From The North Line and 700 Feet From The East Section 15 Township 165 Range 32E NMFM Lea Control 10 Elevation (Show whether DP, REJ, MT, GR, acc.) 4304' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING APORABILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS OTHER: Perforate Describe Proposed or Completed Operations (Clearly state all periverse details, and give periverse data, inclusing estimated data of starting any proposed work) SEE RULE 1103. DOTHER: Perforate 12-30-98 Cleaned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 500 Tother and the completed operations of 152 HCL acid. Reversed acid out. Tested cass to 2000%, 0K. TOOH. Rigged up wireline. TH with agging tools and ran GR/CBL/CCL 1 TOOH with logging tools and rigged down wireline. Shut down. 1-1-2-299 - TH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed 13-99 Rigged up wireline. TH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42. 42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down	Artesia, NM 88210	Anderson Ranch Morrow (gas)	
Section 15 Township 165 Rame 32E NMFM Lea 10 Elvaviation (Skow which to Dr. RES. RT, GR. etc.) 4304' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON ALTERNING CASING COMMENCE OFFILING OPN. PLUG AND ABANDON CAMENCE DRILLING OPN. <td colspand<="" t<="" td=""><td>1650 Feet From The North Line and</td><td></td></td>	<td>1650 Feet From The North Line and</td> <td></td>	1650 Feet From The North Line and	
10 Elevatica (Skow Victiker OF, RES, RT, GR, etc.) 4304' GR 4304' GR Ocheck Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: FROM REMEDIAL WORK PLUG AND ABANDON APORARILY ABANDON CHANGE PLANS LOR ALTER CASING CHANGE PLANS LOR ALTER CASING CHANGE PLANS Describe Proposed or Completed Operations (Clearly state all periferent details, and give periferent detail, and give periferent detail and regreated data of starting any proposed work) SEE RULE 1103. 12-30-98 Clearned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 500 tubinghead. Moved in and rigged up upulling unit. TIH with 4-3/4" bit, scraper and 10 joints of tubing. Shut down. 12-31-98 TIH with remainder of 2-7/8" tubing and tagged PBTD at 12480'. Nippled up BOP. Pickled tubing with 500 gallons of 15% HCL acid. Reversed acid out. Tested cas to 2000#, 0K. TOOH. Rigged up wireline. TIH with 10 hogging tools and rigged down wireline. Shut down. 1-2-99 TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 Rigged down Wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42. 42" holes (6 SFF - Morrow). TOOH with casing guns and rigg	160	Inc.	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: RFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING APORARILY ABANDON CHANGE PLANS PLUG AND ABANDON PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS PLUG AND ABANDON PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS PLUG AND ABANDON PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS PLUG AND ABANDON PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS PLUG AND ABANDON PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS PLUG AND ABANDON PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS PLUG AND ABANDON PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS PLUG AND ABANDON PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB LOR ALTER CASING CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB	10. Elevation (Show whether DF, RKB, KT, G	NMPM Lea County	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: IFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING NPORARILY ABANDON CHANGE PLANS PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS PLUG AND ABANDON IER: OTHER: Perforate PLUG AND ABANDON Describe Proposed or Completed Operations (Clearly state all perimens details, and give periment dates, including estimated date of starting any proposed volt SEE RULE 1103. Noved in and rigged up pulling unit. TIH with 4-3/4" bit, scraper and 100 joints of tubing. Shut down. 12-31-98 TIH with remainder of 2-7/8" tubing and tagged PBTD at 12480'. Nippled up BOP. Pickled tubing with 500 gallons of 15% HCL acid. Reversed acid out. Tested cas to 2000#, 0K. TOOH. Rigged up wireline. THH with logging tools and ran GR/CBL/CCL 11 ToOH with logging tools and ran GR/CBL/CCL 11 ToO			
RFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB PLUG AND ABANDON LOR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB 12-30-98 Cleaned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 500 Jon 100 J011 thing antinged down wirelin	ck Appropriate Box to Indicate Nature of N	-	
PPORARILY ABANDON CHANGE PLANS COMMENCE DRULING OPNS. PLUG AND ABANDONM LOR ALTER CASING COMMENCE DRULING OPNS. PLUG AND ABANDONM LOR ALTER CASING COMMENCE DRULING OPNS. PLUG AND ABANDONM ER:		SUBSEQUENT REPORT OF:	
LOR ALTER CASING CASING CASING CASING CASING CASING TEST AND CEMENT JOB CASING TEST AND TEST AND TEST			
LOR ALTER CASING CASING TEST AND CEMENT JOB DESCRIPS Proposed or Completed Operations (Clearly state all perineent datails, and give perineent dates, including estimated date of starting any proposed work) SEE RULE 1103. OTHER: Perforate Descrips Proposed or Completed Operations (Clearly state all perineent datails, and give perineent dates, including estimated date of starting any proposed work) SEE RULE 1103. 12-30-98 - Cleaned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 5000 joints of tubing. Shut down. 12-31-98 - TIH with remainder of 2-7/8" tubing and tagged PBTD at 12480'. Nippled up BOP. Pickled tubing with 500 gallons of 15% HCL acid. Reversed acid out. Tested cass to 2000#, OK. TOOH. Rigged up wireline. TIH with logging tools and ran GR/CBL/CCL I TOOH with logging tools and rigged down wireline. Shut down. 1-1-2-99 - TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with 3-3/8" casing gun with 5.0" propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and crigged down wireline. TIH with 3-3/8" casing gun with 20K compression. 1-2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. 1-2-469 A wide down BOP. Nippled up tree. 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. 1-2-469 A wide down BOP. Nippled up tree.			
Describe Proposed or Completed Operations (Clearly state all perimens details, and give perimens dates, including estimated date of starting any proposed work) SEE RULE 1103. 12-30-98 - Cleaned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 500 tubinghead. Moved in and rigged up pulling unit. TIH with 4-3/4" bit, scraper and 10 joints of tubing. Shut down. 12-31-98 - TIH with remainder of 2-7/8" tubing and tagged PBTD at 12480'. Nippled up BOP. Pickled tubing with 500 gallons of 15% HCL acid. Reversed acid out. Tested cas to 2000#, OK. TOOH. Rigged up wireline. TIH with logging tools and ran GR/CBL/CCL 1 TOOH with logging tools and rigged down wireline. Shut down. 1-1-2-99 - TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. TH Operations Technician NATURE AND	<u></u>		
Describe Proposed or Completed Operations (Clearly state all perimene details, and give perimenet dates, including estimated date of starting any proposed work) SEE RULE 1103. 12-30-98 - Cleaned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 500 tubinghead. Moved in and rigged up pulling unit. TIH with 4-3/4" bit, scraper and 10 joints of tubing. Shut down. 12-31-98 - TIH with remainder of 2-7/8" tubing and tagged PBTD at 12480'. Nippled up BOP. Pickled tubing with 500 gallons of 15% HCL acid. Reversed acid out. Tested cas to 2000#, OK. TOOH. Rigged up wireline. TIH with logging tools and ran GR/CBL/CCL 1 TOOH with logging tools and rigged down wireline. Shut down. 1-1-2-99 - TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-3-99 Kusty Klein . MARTINE Rusty CLEARED . MARTINE RUSTY KLEINER . MARTINE RUSTY . MARTINE R		erforate	
<pre>word Ste RULE 1103. 12-30-98 - Cleaned location, set and tested anchors. Installed 11" 5000 X 7-1/16" 500 tubinghead. Moved in and rigged up pulling unit. TIH with 4-3/4" bit, scraper and 10 joints of tubing. Shut down. 12-31-98 - TIH with remainder of 2-7/8" tubing and tagged PBTD at 12480'. Nippled up BOP. Pickled tubing with 500 gallons of 15% HCL acid. Reversed acid out. Tested cass to 2000#, OK. TOOH. Rigged up wireline. TIH with logging tools and ran GR/CBL/CCL 1 TOOH with logging tools and rigged down wireline. Shut down. 1-1-2-99 - TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-299 Awabbed. Shut well 10 mms Operations Technician Date Jan. 5, 1 mms Operations</pre>			
tubinghead. Moved in and rigged up pulling unit. TIH with 4-3/4" bit, scraper and 10 joints of tubing. Shut down. 12-31-98 - TIH with remainder of 2-7/8" tubing and tagged PBTD at 12480'. Nippled up BOP. Pickled tubing with 500 gallons of 15% HCL acid. Reversed acid out. Tested cas to 2000#, OK. TOOH. Rigged up wireline. TIH with logging tools and ran GR/CBL/CCL 1 TOOH with logging tools and rigged down wireline. Shut down. 1-1-2-99 - TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 Swabbed. NATURE Musty Klein . THE MARK Rusty Klein . THE MINE MUST WILIAMS			
joints of tubing. Shut down. 12-31-98 - TIH with remainder of 2-7/8" tubing and tagged PBTD at 12480'. Nippled up BOP. Pickled tubing with 500 gallons of 15% HCL acid. Reversed acid out. Tested cas to 2000#, OK. TOOH. Rigged up wireline. TIH with logging tools and ran GR/CBL/CCL 1 TOOH with logging tools and rigged down wireline. Shut down. 1-1-2-99 - TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and rigged down wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 wabbed. Multi Welf in the down bid for of my knowledge and bid. NATURE Musty Klein . THE Operations Technician DATE Jan. 5, 1 THE OPERATIONS WILLIAMS	in and rigged up pulling unit TT	Installed II" SUUU X $/-1/16$ " 5000 With $4-3/4$ " bit corpor and 100	
BOP. Pickled tubing with 500 gallons of 15% HCL acid. Reversed acid out. Tested cas to 2000#, OK. TOOH. Rigged up wireline. TIH with logging tools and ran GR/CBL/CCL 1 TOOH with logging tools and rigged down wireline. Shut down. 1-1-2-99 - TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 Ambed. Shut well in mage Operations Technician NATURE Austy Klein . TELEPHONE NO. 505/7 TELEPHONE NO. 505/7	Shut down.	•	
to 2000#, OK. TOOH. Rigged up wireline. TIH with logging tools and ran GR/CBL/CCL 1 TOOH with logging tools and rigged down wireline. Shut down. 1-1-2-99 - TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 Wabbed Shut Well in mus Operations Technician Date Jan. 5, 1 Watty Mie Morrow Rusty Klein . THERMONE NO. 505/7 THERMONE NO. 505/7	remainder of $2-7/8"$ tubing and ta	ged PBTD at 12480'. Nippled up	
TOOH with logging tools and rigged down wireline. Shut down. 1-1-2-99 - TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 & Wabbed and South Well in mrs. Operations Technician DATE Jan. 5, 1 THERMONENO. 505/7 THERMONENO. 505/7 THERMONENO. 505/7	g with 500 gallons of 15% HCL acid	Reversed acid out. Tested casing	
1-1-2-99 - TIH with seating nipple and 216 joints of 2-7/8" tubing (7002'). Swabbed tubing/annulus to 6300'. TOOH. Shut well in. 1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 Swabbed. NATURE Rusty Klein Rusty Klein THE PROPERTY ANS	ools and rigged down wireline. Sh	egging cools and ran GK/CBL/CCL log.	
1-3-99 - Rigged up wireline. TIH with 3-3/8" casing gun with 5' propellant sleeve and perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 Wabbed. Shut Well in rety couly the informatice above in the and complete to the feet of my knowledge and belief. NATURE Rusty Klein . Rusty Klein . Mary CH3:S WILLIAMS	seating nipple and 216 joints of		
perforated 12304-12310' w/42 .42" holes (6 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints o 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 KWabbed of MUL Well in organize to the feet of my knowledge and belef. NATURE Musty File information around it for the feet of my knowledge and belef. NATURE Rusty Klein . THE PROVENO. 505/7 THE PROVE NO. 505/7		· · · · · ·	
rigged down wireline. TIH with Arrow set packer with 1.875" on/off tool, 377 joints on 2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 & Wabbed annulus to 1500 psi. Swabbing. 1-4-99 & Wabbed annulus to 1500 psi. Swabbing. THE Operations Technician Date Jan. 5. 1 THE PROVENO. 505/7 THE PROVENO. 505/7 THE SPACE for State Use)	vireline. TIH with $3-3/8"$ casing $310!$ w/42 42" balage (6 SDF)	un with 5' propellant sleeve and	
2-7/8" tubing. Nippled down BOP. Nippled up tree. Set packer with 20K compression. Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 Wabbed. Shull Well in the feat of my knowledge and bellet. NATURE Usty June June Jan. 5, 1 Rusty Klein			
Loaded & pressured annulus to 1500 psi. Swabbing. 1-4-99 Swabbed Shut Well in mby centry the information above in the and compares to the feet of my knowledge and bellef. NATURE Use Rusty Klein . Operations Technician DATE Jan. 5, 1 THE APPECNE NO. 505/7 is space for State Use)			
NATURE Austy Jun DATE Jan. 5, 1 THE OPERATIONS NO. 505/7 THE SPHERE NO. 505/7 In space for State Use)	annulus to 1500 psi. Swabbing.		
INATURE NATURE			
is space for State Use)	lin Operati	ons Technician Jan. 5, 1999	
AS SPACE FOR STALE UND DEVICIENT OF CHERIS WILLIAMS ORIGINAL SIGNED BY CHERIS WILLIAMS DISTRICT I SCHERTVISOR DISTRICT I SCHERTVISOR			
ORIGINAL SIGNED BY CHAID VILLE	in .	THE JUPHONE NO. 505/748-1	
DATE DATE DATE DATE		THE JUPHONE NO. 505/748-1	
NDITIONS OF APPROVAL, IF ANY:			