

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-025-34541
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> <i>P</i>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Dry Hole	
2. Name of Operator David H. Arrington Oil & Gas, Inc	
3. Address of Operator P.O. Box 2071, Midland, Texas 79702	
4. Well Location	

7. Lease Name or Unit Agreement Name: Prince Nymph
7. Well No. 1
8. Pool name or Wildcat Caudill-Permo Upper Penn

*2-24-01 Talked
to Dora
She will send
corrected C103
on PA*

from the South line and 943' feet from the East line
T15S Range 36E NMPM County Lea
(Show whether DR, RKB, RT, GR, etc.)

Box to Indicate Nature of Notice, Report or Other Data	
Abandon <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
NS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
<input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
<input type="checkbox"/>	OTHER: <input type="checkbox"/>

Clearly state all pertinent details, and give pertinent dates, including estimated date of completion.

2/4/00- Lay 6 drill collar's, trip in hole to bottom of casing. Trip in hole open ended. Circ.
Set 1st plug at 9865' and lay down drill pipe.
Set 2nd plug at 8435' and lay down drill pipe.
Set 3rd plug at 6345' and lay down drill pipe.
Set 4th plug at 4969' and lay down drill pipe. Circ. Tag plug at 4665' and lay down drill pipe.
2/5/00 Lay down drill pipe and set plugs, ND and RD. Rig released at 12:30 p.m.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Chuck Sledge* TITLE Engineer DATE 7/10/01

Type or print name Chuck Sledge Telephone No. (915) 682-6685

(This space for State use)

APPROVED BY *Billy E. Lutton* TITLE DATE

Conditions of approval, if any: