Submit 3 Copies To Appropriate District	State of N	State of New Mexico		Form C-103		
Office		Energy, Minerals and Natural Resources			Revised March 25, 1999	
District I	Lifer By, Willier and	Energy, winerals and rataria research			WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVATION DIVISION			30-025-34607 5. Indicate Type of Lease		
811 South First, Artesia, NM 88210	2040 South Pacheco					
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			6. State Oil & Ga		
District IV	Santa PC, INVI 07505			6. State Oli & Oa 24466	S Lease No.	
2040 South Pacheco, Santa Fe, NM 87505	TO AND DEPODITE ON	IWEIIS			Unit Agreement Name:	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:				Royal Humpy		
Oil Well 🔽 Gas Well 🗋 Other				8. Well No.		
2. Name of Operator				1		
David H. Arrington Oil & Gas, Inc				9. Pool name or Wildcat		
3. Address of Operator	9702			Diamond Strawn		
P.O. Box 2071, Midland, Texas 7 4. Well Location	<u>)102</u>					
				fact from the	East line	
Unit Letter I :1615	'feet from theSo	outh	_line and _1161	leet nom me		
Section 16	Township	16S	Range 36E	NMPM	County Lea	
Section 10	10. Elevation (Show w	whether DR	R, RKB, RT, GR, etc	c.)		
	2004' CD 2010'	' KR				
11. Check Ar	opropriate Box to Inc	dicate Na	ture of Notice,	Report or Other I	Jala DOPT OF:	
NOTICE OF INTENTION TO: SU						
			REMEDIAL WOR			
	CHANGE PLANS		COMMENCE DRILLING OPNS. C PLUG AND ABANDONMENT			
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB			
			OTHER: Reco	mpletion not	Successful I	
OTHER: 12. Describe proposed or complete	d anarations (Clearly	state all per	1.1.1.1. and	give pertinent dates	including estimated date	
of starting any proposed work).	. SEE RULE 1103. For	r Multiple (Completions: Atta	ch wellbore diagram	of proposed completion	
or recompilation.						
2/28/01 NU BOP & pulled 10 jts. 3/01/01 Pulled & tally tbg. RU C	omputalog & run gauge	ering. Run	CIBP & set @ 11	,500'. RD Computal	log. Ran 20	
its of tbg.		2	aire tha			
3/02/01 - Ran tbg to 10,723'. Pulle 3/03/01 - Test casing to 500 psi, ok	C Hot oiled down the w	v/50 BO. R	Reverse circ oil out	of tbg & displace ho	ole w/2%	
KCL. Spot & rig down	Halliburton. Pulled tbg	•		10 007? Pr ast pp	oker Ran	
KCL. Spot & rig down 3/04/01 – RU Computalog & perf 1	10,708'-10,720'. RD Co	omputalog.	Ran packer w/tbg	g to 10,807 & set pa	CKCI. IXan	
swab FL @ surf.			1600' Swah well	down good gas.		
swab FL @ surf. 3/05/01 – Prep to acid. SITP 875. 3/06/01 - Flow test. Acidize. Blee	Bled down I nr. Kan s	@ surf. Sv	vab well down to 4	800'. Well started f	lowing &	
3/06/01 - Flow test. Acidize. Ble	d dowii & raii swab i b s					
open well up. Well died 3/7-8/01 – Ran swab test.	4.					
	ll for 7 days.		(I DIT /104)	to of the		
3/09/01 – Ran bomb. Bomb in we 3/27/01 – MIRU El Toro Well Ser	vice. Released packer &	& POOH w	/tbg. RIH W/194 J	is of tog.		
I hereby certify that the informatio	n above is true and com	ipiete to un	e best of my know		10 1	
	4	TITLE	Engineer		DATE5/22/01	
SIGNATURE	6				e No. (915) 682-6685	
Type or print name Chuck Slee	dge			Telephone	110. ()10) 002 0000	
(This space for State use)		TITLE			DATE	
APPPROVED BY	274 - 1 - 5 - 7 - 7	111LC				
APPPROVED BY Conditions of approval, if any:	* /* *					

.

· · · ·

.



Cont. for #12- (Page 2 / C-103)

3/28/01 - Finish RIH w/tbg. Set retainer w/338 jts of 2 7/8" N-80 tbg @ 11,657'. RU Halliburton. Mixed & pump 50 sxs Class "H" cmt & 4/10% Halad 322. Tailed w/50 sxs Class "H" Neat. Obtained a 4000# walking squeeze. Pumped 58 sxs into formation. Left 4 sxs in casing & reversed out 38 sxs. POOH w/tbg.

3/29/01 - RIH w/334 jts of 2 7/8" N-80 tbg. Tag cement retainer @ 10,657'. Drilled out retainer & cement down to 10,728'. Circ hole clean. Tested casing to 500#, held ok.

- 3/30/01 Tagged CIBP @ 11,500'. Drilled out CIBP & RIH w/tbg to PBTD @ 11,698'. POOH w/tbg. LDDC's.
- 4/02/01 RIH w/367 jts of 2 7/8" tbg. TAC would not set.
- 4/03/01 POOH w/tbg. RIH w/sand line & tag PBTD @ 11,698'. RIH w/tbg.
- 4/04/01 ND BOP. Set TAC @ 11,585'. NU pumping tee. RIH w/395 rods. Shut down to repair rod tongs. 4/05/01 - Ran rods. Spaced out pump. Hung well on. Loaded tbg w/50 BW. Test tbg to 500#, held ok. Released rig.

Return Strawn perfs to production.

