Submit 3 Copies To Appropriate District State of New 1		Form C-103	
District I Energy, Minerals and N 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	Revised March 25, 1999	
District II 1301 W. Grand Avenue, Artesia, NM 88210 OIL CONSERVATIO	N DIVISION 30-025-34662		
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1000 Rio Brazos Rd., Aztec, NM 87410	stancis Dr. 5. Indicate Type of STATE		
District IV Santa Fe, NM	87505 6. State Oil & G		
1220 S. St. Francis Dr., Santa Fe, NM 87505		as Lease NU.	
SUNDRY NOTICES AND REPORTS ON WEI (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10) PROPOSALS.)	LUG BACK TO A	• Unit Agreement Name: • Com.	
1. Type of Well:	1		
Oil Well ✓ Gas Well Other 2. Name of Operator Chevron USA, Inc.	8. Well No.		
		Anderson Ranch	
3. Address of Operator 15 Smith Rd. Midland, Tx 797	9. Pool name or	·Wildcat	
4. Well Location			
Unit Letter N : 660 feet from the south line and 2310 feet from the west line			
Section 14 Township 16-S Range 32-E NMPM County Lea			
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS	RARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		
OTHER:	OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.			
1. Set 5 1/2 CIBP @2870 ND, well head,Found no 5 1/2 csg, talk to Bill P. & Gary W. about work done.			
2. Spot 60sx fr/2869-2627, WOC Tag @ 2630			
 Displace hole w/MLF 9.5 # Brine w/25 # Gel P/BBL. Spot 60sx fr/1300-1100(T-salt) 			
5. Spot 60sx fr/625-425(11 3/4 shoe)WOC Tag @ 400			
6. Perf @ 300, pressure up to 2000 lbs no blead off.			
7. Circ hole w/90sx fr/350-surf			
8. Rig down. Install dry hole marker. 12-12-02			
		$\mathcal{U}_{\mathcal{U}}$, $\mathcal{U}_{\mathcal{U}}$	
Approved as to Plugging of the Well B	re.		
Liability under bond is retained until		$\sim \frac{1}{2} \left[\frac{1}{2} \left[\frac{1}{2} \left[\frac{1}{2} \right] \right] \right]$	
Surface restoration is completed.			
I hereby certify they use intogration above is true and complete to the best of my knowledge and belief.			
SIGNATURE			
Type or print name JIMMY BAGLEY Telephone No.9155208756			
(This space for State use) COUCHNAL SIGNED BY GART WE WINK			
	OA TVF IL/STAFF MANAGER	DATREC 1 9 2119	
Conditions of approval, if any:			

. -