Submit 3 Copies To Appropriate District	nit 3 Copies To Appropriate District State of New Mexico		Form C-103		
Office	Energy, Minerals and Natural Resources		Revised March 25, 1999		
District 1 1625 N. French Dr., Hobbs, NM 38240			WELL API NO.		
Product of the product of the second		- ON AN AN ANY AN	30-025-34752		
og i Soutier (St. Andsla, Not 2021)	OIL CONSERVATION		15 Indicate Type /	sê (esce	
and a second state	1220 South St. Fra	neis Dr.	STATE		
ان باغان کار بار در در این محمد میرود کو کار کو ماداری مراجع	Santa Eo. NAV S	77.95			i
(220 S. St. Francis Or , Santa Fe, NM			1		,
87505			VA-753		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:			7. Lease Name or Unit Agreement Name [.] C. O. Jones ATK State		
Oil Well X Gas Well	Other		7. Well No.		
2. Name of Operator					
Yates Petroleum Corpor	ation		#2		
3. Address of Operator			8. Pool name or Wildcat		
105 S. 4 th Street Artesi	ia, NM 88210		Tonwsend	Permo Upper Pen	າກ
4. Well Location Unit Letter <u>M</u> : 380 feet from the <u>South</u> line and <u>330</u> feet from the <u>West</u> line Section 11 Terreship 14S Barger 355 NMDM					
	Township 16S Range	35E N	мрм Lea	County	
	Township16SRange10.Elevation (Show whether D	35E N R, RKB, RT, GR, et	мрм Lea		
Section 11	Township16SRange10.Elevation (Show whether D3987	35E N DR, RKB, RT, GR, et '' GR	MPM Lea	County	1
Section 11 11. Check A	Township16SRange10.Elevation (Show whether D3987ppropriate Box to Indicate N	35E N <i>R</i> , <i>RKB</i> , <i>RT</i> , <i>GR</i> , <i>et</i> '' GR lature of Notice,	ImpLeatc.)ImpReport or Other	County	
Section 11	Township16SRange10.Elevation (Show whether D3987ppropriate Box to Indicate N	35E N <i>R</i> , <i>RKB</i> , <i>RT</i> , <i>GR</i> , <i>et</i> '' GR lature of Notice,	MPM Lea	County Data PORT OF:	
Section 11 11. Check A	Township16SRange10.Elevation (Show whether D3987ppropriate Box to Indicate N	35E N <i>R</i> , <i>RKB</i> , <i>RT</i> , <i>GR</i> , <i>et</i> '' GR lature of Notice,	Impm Lea tc.) Import or Other Report or Other Import or Other BSEQUENT REI	County	
Section 11 11. Check A NOTICE OF IN	Township 16S Range 10. Elevation (Show whether D 3987 ppropriate Box to Indicate N TENTION TO:	35E N PR, RKB, RT, GR, et " "GR " lature of Notice, SUE	MPM Lea tc.) Image: state st	County Data PORT OF: ALTERING	
Section 11 11. Check A 11. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Township 16S Range 10. Elevation (Show whether D 3987 ppropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE	35E N DR, RKB, RT, GR, et " "GR " Iature of Notice, SUE REMEDIAL WOR COMMENCE DR CASING TEST A	Impm Lea tc.) Import of Other Import of	County Data PORT OF: ALTERING CASING X PLUG AND	
Section 11 11. Check A NOTICE OF IN PERFORM REMEDIAL WORK	Township 16S Range 10. Elevation (Show whether D 3987 ppropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS	35E N DR, RKB, RT, GR, et " "GR " Iature of Notice, SUE REMEDIAL WOR COMMENCE DR	Impm Lea tc.) Import of Other Import of	County Data PORT OF: ALTERING CASING X PLUG AND	
Section 11 11. Check A 11. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Township 16S Range 10. Elevation (Show whether D 3987 ppropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE	35E N PR, RKB, RT, GR, et " "GR SUE lature of Notice, SUE REMEDIAL WOF COMMENCE DF CASING TEST A CEMENT JOB	Impm Lea tc.) Import of Other Import of	County Data PORT OF: ALTERING CASING X PLUG AND ABANDONMENT	
Section 11 11. Check A 11. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	Township 16S Range 10. Elevation (Show whether D 3987 ppropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	35E N R, RKB, RT, GR, et "GR Tature of Notice, SUE REMEDIAL WOF COMMENCE DF CASING TEST A CEMENT JOB OTHER: Perfora	MPM Lea tc.) Image: Second state stat	County Data PORT OF: ALTERING CASING X PLUG AND ABANDONMENT zone X	 X
Section 11 11. Check A 11. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	Township 16S Range 10. Elevation (Show whether D) 3987 ppropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Derations. (Clearly state all pertine RULE 1103. For Multiple Complexity Yer Strawn open hole. 10-10917', 36 holes, .42" hole well started flowing.	35E N R, RKB, RT, GR, et "GR Tature of Notice, SUE REMEDIAL WOF COMMENCE DR CASING TEST A CEMENT JOB OTHER: Perforate ent details, and give etions: Attach well	Impm Lea Report or Other Impm BSEQUENT REI Impm RK Impm RILLING OPNS. Impm ND Impm te and acidize to add Impm pertinent dates, inclubore diagram of prop	County Data PORT OF: ALTERING CASING X PLUG AND ABANDONMENT zone X uding estimated date of bosed completion or	 X
Section 11 11. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE I recompilation. 9/21/01 - Set RBP at 11000' ov 9/24/01 - Perforate Cisco 109 9/25/01 - Made 7 swab runs, v	Township 16S Range 10. Elevation (Show whether D) 3987 ppropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Derations. (Clearly state all pertine RULE 1103. For Multiple Complexity Yer Strawn open hole. 10-10917', 36 holes, .42" hole well started flowing.	35E N R, RKB, RT, GR, et "GR Tature of Notice, SUE REMEDIAL WOF COMMENCE DR CASING TEST A CEMENT JOB OTHER: Perforate ent details, and give etions: Attach well	Impm Lea Report or Other Impm BSEQUENT REI Impm RK Impm RILLING OPNS. Impm ND Impm te and acidize to add Impm pertinent dates, inclubore diagram of prop	County Data PORT OF: ALTERING CASING X PLUG AND ABANDONMENT zone X uding estimated date of bosed completion or	 X
Section 11 11. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE I recompilation. 9/21/01 - Set RBP at 11000' ov 9/24/01 - Perforate Cisco 109 9/25/01 - Made 7 swab runs, v	Township 16S Range 10. Elevation (Show whether D) 3987 ppropriate Box to Indicate N TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Derations. (Clearly state all pertine RULE 1103. For Multiple Complexity Yer Strawn open hole. 10-10917', 36 holes, .42" hole well started flowing.	35E N R, RKB, RT, GR, et "GR Tature of Notice, SUE REMEDIAL WOF COMMENCE DR CASING TEST A CEMENT JOB OTHER: Perforate ent details, and give etions: Attach well	Impm Lea Report or Other Impm BSEQUENT REI Impm RK Impm RILLING OPNS. Impm ND Impm te and acidize to add Impm pertinent dates, inclubore diagram of prop	County Data PORT OF: ALTERING CASING X PLUG AND ABANDONMENT zone X uding estimated date of bosed completion or	 X

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

505

SIGNATURE 4. K. Hupe	TITLE Engineering Technician DATE	<u>December 28, 2001</u>
Type or print name Susan Herpin	URIGINAL SIGNED BY Telephon	ne No. 505-748-1471
(This space for State use) APPPROVED BY	PAUL F. KAUTZ TITLE PETROLEUM ENGINEER	MAY 2 2 2002 Date
Conditions of approval, if any:	2A AURI Shoobar	Strange