District I PO Box 1980, Hobbs, NM 88241-1980 District II PO Drawer DD, Artesia, NM 88211-0719 District III 1000 Rio Brazos Rd., Aztec, NM 87410 **District IV** PO Box 2088, Santa Fe, NM 87504-2088

•

State of New Mexico Energy, Minerals & Natural Resources Department

## OIL CONSERVATION DIVISION PO Box 2088 Santa Fe, NM 87504-2088

Form C-101 Revised February 10, 1994 Instructions on back Submit to Appropriate District Office State Lease - 6 Copies Fee Lease - 5 Copies

## AMENDED REPORT

## APPLICATION FOR PERMIT TO DRILL, RE-ENTER, DEEPEN, PLUGBACK, OR ADD A ZONE

			I	Operator Na	me and Address.			·		10	GRID Number 575
Yates Pe 105 Sout	-				J						
Artesia,			et								<b>API Number</b> 25–34752
<sup>4</sup> Property Code				\$ P	<sup>5</sup> Property Name				<u> </u>	' Well No.	
25027 C. O. Jones ATK State											2
					<sup>7</sup> Surface	Location	-				
UL or lot no. Section		Township Range		Lot Ida	Feet from the	North/South line		Feet from the East/		Vest line	County
М		16S	35E	2	380	South		330	V	Vest	Lea
	lk	<sup>8</sup> Pr	oposed	Bottom	Hole Locat	ion If Diff	erent	From Sur	· · · · · · · · · · · · · · · · · · ·		
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South	T T	Feet from the		West line	County
N	11	16S	35E		361	South		2299	We	est	Lea
Tow	nsend gnated	Perr		oper P		<u></u>		" Propos			
<sup>11</sup> Week 7	Type Code	ı	' Well Type	Cada	<sup>13</sup> Cable	Rolen	t	<sup>4</sup> Lease Type Co	de	<sup>14</sup> Grou	nd Level Elevation
				Code		-					
A "Multiple		O " Proposed D		Death	Pulling "For		S "Contracto			3987 ' GR " Spud Date	
•		PBTD 10975'		-							
Dua	1				Cisc		Drog	Unknown			ASAP
					g and Cement Program setting Depth Sacks of Cement Estimated T					Estimated TOC	
26"		Casing Size		Casing weight/loot						·	Estimated TOC
17-1/2"		20"		48#		40'		In place			
17-1/2"		<u>13-3/8"</u> 9-5/8"		36# & 40#		<u>407</u> 4743		In place In place			
		7"		1				-			· · · · · · · · · · · · · · · · · · ·
8-3/4"		<u> </u>		26#		11412'		In place			
zone. Describe Propose fo follows: 1. Set fo Pressure 2. Nippl 3. Insta with 9.2 test pack	the blowout to add olankin up on le down all val ppg cu cer. P	prevention p perfora g plug tubing tree a ve on t t bring 00H wit	in 2.2 to 150 and nip cubing while ch 2-7/	any. Use ad in Cis 25" F n 00 psi ople up and di e rever 78" 6.5 CINUED	ditional sheets if a co and the for 15 mir BOP. sengage tu sing to pi # L-80 tub ON NEXT PA	en dual wi pottom of autes to a bing from t. Press ing. GE:	ith S 10' cest pac sure	Strawn ope sub below blanking ker on/of up on cas	en ho w pac plug ff to sing	ele con eker se ool. I to 250	00 psi to
<sup>13</sup> I hereby certify that the information given above is true and complete to the best of my knowledge and belief.						OIL CONSERVATION DIVISION					
Signature: Justing Un						Approved by: OPPIGINAL SIGNED BY					
- V	July 1	$p_{-}$	fin.					<u>Arian</u>	<u> iai s</u> i	IGNED	BY
Printed name:	Rusty	Klein	lin			itle:		<u></u>		IGNED I VI∕NK	3Y
Title	Rusty Operation		chnici	 an	Т			<u></u>	Expiralio	IGNED- MNX a-Date!	<b>BY-</b>

Attached 🛛

505-748-1471

May 10, 2000