Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-183 Revised 1-1-29

\_ DATE -

DISTRICT! OIL CONSERVATION DIVISION	
P.O. Box 1980, Hobbs, NM 88240  OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210  DISTRICT III 1000 Rio Brazzos Rd., Azzec, NM \$7410	30-025-35006
	5. Indicate Type of Lease STATE FEE X
	6. State Oil & Gas Lease No.
CUMPRY NOTICES AND DEPOSITS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well:	DONGE 15
WELL OTHER NEW Drilling	BOYCE 15
2. Name of Operator	8. Well No.
Chesapeake Operating, Inc.  3. Address of Operator	9. Pool name or Wildcat
P. O. Box 18496, Okla. City, OK 73154-0496	NW Shoebar Strawn
4. Well Location  Unit Letter H : 2310 Feet From The North Line and	341 For The East
Unit Letter 1 : 2310 Feet From The NOTE II Line and	J41 Feet From The Last Line
Section 15 Township 16S Range 35E	NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.	)
GR: 3984'	Percet or Other Data
<ol> <li>Check Appropriate Box to Indicate Nature of Notice</li> </ol>	, Report, or Outer Data
NOTICE OF INTENTION TO	<del>-</del>
NOTICE OF INTENTION TO:	UBSEQUENT REPORT OF:
	<del>-</del>
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	UBSEQUENT REPORT OF:  ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	UBSEQUENT REPORT OF:  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND	UBSEQUENT REPORT OF:  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND	UBSEQUENT REPORT OF:  ALTERING CASING  JING OPNS. PLUG AND ABANDONMENT  CEMENT JOB  "CSg; Rig Release
PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  OTHER: OTHER: OTHER: OTHER: 5-1/2  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD	UBSEQUENT REPORT OF:  ALTERING CASING  JING OPNS. PLUG AND ABANDONMENT  CEMENT JOB  "CSg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ,
PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  OTHER: OTHER: OTHER: OTHER: 5-1/2  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD  DUMP 15 BFW, 200 bb1s brine & 24 bb1s Mud Clear	UBSEQUENT REPORT OF:  ALTERING CASING  JING OPNS. PLUG AND ABANDONMENT  CEMENT JOB  "Csg: Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx
PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clear 35/65 POZ. 12.4 PPG, 1.99 yield, cont w/295 sx	ALTERING CASING  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG,
PLUG AND ABANDON REMEDIAL WORK  COMMENCE DRILL  CASING TEST AND  CHARGE PLANS  CASING TEST AND  CASING TEST AND  COTHER: 5-1/2  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clean 35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx 1.63 yield, begin stage 2, 24 bbls Mud Clean 1	ALTERING CASING  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz +
PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  OTHER: OTHER: OTHER: 5-1/2  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clear 35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx 1.63 yield, begin stage 2, 24 bbls Mud Clean 1 additives, 12.5 PPG, 1.94 yield, cont w/220 sx RD cmt head, PU BOPs, set slips with 120,000#,	ALTERING CASING  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield,
PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  OTHER:  OTHER:  OTHER:  OTHER:  O5/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD  pump 15 BFW, 200 bbls brine & 24 bbls Mud Clear  35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx  1.63 yield, begin stage 2, 24 bbls Mud Clean ladditives, 12.5 PPG, 1.94 yield, cont w/220 sx	ALTERING CASING  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield,
PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  OTHER: OTHER: OTHER: 5-1/2  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clear 35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx 1.63 yield, begin stage 2, 24 bbls Mud Clean 1 additives, 12.5 PPG, 1.94 yield, cont w/220 sx RD cmt head, PU BOPs, set slips with 120,000#,	ALTERING CASING  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield,
PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  OTHER: OTHER: OTHER: 5-1/2  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clear 35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx 1.63 yield, begin stage 2, 24 bbls Mud Clean 1 additives, 12.5 PPG, 1.94 yield, cont w/220 sx RD cmt head, PU BOPs, set slips with 120,000#,	ALTERING CASING  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield,
PLUG AND ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  CHER:  CASING TEST AND  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND  CHANGE PLANS  CHANGE PLA	ALTERING CASING  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield,
PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  OTHER: OTHER: OTHER: 5-1/2  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clear 35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx 1.63 yield, begin stage 2, 24 bbls Mud Clean 1 additives, 12.5 PPG, 1.94 yield, cont w/220 sx RD cmt head, PU BOPs, set slips with 120,000#,	ALTERING CASING  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield,
ERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILL  CASING TEST AND  OTHER:  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clear 35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx 1.63 yield, begin stage 2, 24 bbls Mud Clean 1 additives, 12.5 PPG, 1.94 yield, cont w/220 sx RD cmt head, PU BOPs, set slips with 120,000#,	ALTERING CASING  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield,
PLUG AND ABANDON REMEDIAL WORK  EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  OTHER: OTHER: OTHER: 5-1/2  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clear 35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx 1.63 yield, begin stage 2, 24 bbls Mud Clean 1 additives, 12.5 PPG, 1.94 yield, cont w/220 sx RD cmt head, PU BOPs, set slips with 120,000#, 05/15/00 Release Nabors Drilling Rig #319 @ 8:00 a.m.	ALTERING CASING  ALTERING CASING  JING OPNS.  PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield,
PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING CASING TEST AND CHANGE PLANS COMMENCE DRILLING CASING TEST AND CHANGE PLANS COMMENCE DRILLING CASING TEST AND CHER: 5-1/2  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clean 35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx 1.63 yield, begin stage 2, 24 bbls Mud Clean 1 additives, 12.5 PPG, 1.94 yield, cont w/220 sx RD cmt head, PU BOPs, set slips with 120,000#, 05/15/00 Release Nabors Drilling Rig #319 @ 8:00 a.m.	ALTERING CASING  JNG OPNS. PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield, NU tree, clean mud tanks
PLUGAND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  CASING TEST AND  OTHER: OTHER: OTHER: 5-1/2  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clear 35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx 1.63 yield, begin stage 2, 24 bbls Mud Clean 1 additives, 12.5 PPG, 1.94 yield, cont w/220 sx RD cmt head, PU BOPs, set slips with 120,000#, 05/15/00 Release Nabors Drilling Rig #319 @ 8:00 a.m.	ALTERING CASING  JNG OPNS. PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield, NU tree, clean mud tanks
PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLI CASING TEST AND OTHER: OTHER: OTHER: OTHER: And give pertinent dates, work) SEE RULE 1103.  05/14/00 Run 271 jts 5-1/2" N-80 & P-110 LTC casing, RD pump 15 BFW, 200 bbls brine & 24 bbls Mud Clean 35/65 POZ, 12.4 PPG, 1.99 yield, cont w/295 sx 1.63 yield, begin stage 2, 24 bbls Mud Clean I additives, 12.5 PPG, 1.94 yield, cont w/220 sx RD cmt head, PU BOPs, set slips with 120,000#, 05/15/00 Release Nabors Drilling Rig #319 @ 8:00 a.m.	ALTERING CASING  JNG OPNS. PLUG AND ABANDONMENT  CEMENT JOB  "Csg; Rig Release  including estimated date of starting any proposed  csg crew. RU cmt head, circ, n 2, cmt 1st stg w/335 sx 15/61 Poz + additives, 13 PPG, , cmt w/620 sx 35/65 Poz + C1. H, 15.6 PPG, 1.18 yield, NU tree, clean mud tanks

- TILE -

CONDITIONS OF APPROVAL, IF ANY:

