

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-35078
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Mayfly 14 State Com
8. Well No. 7
9. Pool name or Wildcat Shoe Bar; Strawn, North
4. Well Location Unit Letter A : 330 feet from the North line and 330 feet from the East line Section 14 Township 16S Range 35E NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3975

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
EOG Resources Inc.

3. Address of Operator
P.O. Box 2267 Midland, Texas 79702

4. Well Location

Unit Letter **A** : **330** feet from the **North** line and **330** feet from the **East** line
Section **14** Township **16S** Range **35E** NMPM County **Lea**

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3975

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: **Recompletion to Strawn** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

02/05/03 MIRU. RIH & released 7" packer. Pooh w/ 2 7/8" tubing and packer. TIH w/ 7" cement retainer set @ 10858'.
02/06/03 Squeeze Cisco perforations 10926-10954. Mix and pump 50 sx Class H.
02/07/03 Drill out retainer, clean out hole to 11091.
02/08/03 TIH mix and pump 50 sx Class H Neat. Spot from 10960 to 10548. Pumped 28 sx into formation. TOC @ 10672'.
02/09/03 Tag top of cement @ 10672, drilled out to 10967. Tested squeezed perfs to 600 psi. Continue drill out to 11594.
02/10/03 Spot 250 gal 15% NE Acid from 11230 to 11388.
02/11/03 Perforate Strawn 11352 to 11388, 2 SPF, 120 degree phasing, (0.46" hole, 72 holes).
02/13/03 Acidized w/ 4000 gal 15% NEFE acid.
02/14/03 Swab and flow test. Turned to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stan Wagner TITLE Regulatory Analyst DATE 2/20/03

Type or print name Stan Wagner

Telephone No. 915 686 3689

(This space for State use)

ORIGINAL SIGNED BY

PAUL F. KAUTZ

APPROVED BY _____ TITLE PETROLEUM ENGINEER DATE 2/20/03

Conditions of approval, if any:

20 Townsend Mission North

