Submit 3 Copies To Appropriate District	Q					
Office	State of New Mexico			Form C-103		
District I	Energy, Minerals a	and Natural	Resources	Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240 District II	8240			WELL API NO.		
811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-35079		
District III 1220 South St. Francis Dr.			5. Indicate Type	of Lease		
1000 Rio Brazos Rd., Aztec. NM 87410			STATE [FEE X		
District IV Santa Fe, NM 87505			6. State Oil & C			
1220 S. St. Francis Dr., Santa Fe, NM 87505				o. Blate on & C	Jus Lease IV.	
	CEC AND DEDODTE ON	LWELLC				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			/. Lease Name of	Unit Agreement Name:		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						
PROPOSALS.)				Arreguy AVP	Com	
1. Type of Well:						
Oil Well Gas Well X Other						
2. Name of Operator				7. Well No.		
Yates Petroleum Corporation				#1		
3. Address of Operator	8. Pool name or	Wildoot				
105 S. 4th Street Artes	ia, NM 88210	RECE				
7,1103	14) THIN 00210	. 0CD - A	RIESIA (57)	Wildcat M	orrow	
4. Well Location		<u>ئ.</u> بىشى				
		The state of				
Unit Letter P: 660	feet from the South	l line on		C of Frank	•	
	rect from the <u>50011</u>	i inic an	d <u>660</u> feet	from the <u>East</u>	line	
Section 24	Township 15\$	Range 34	F NIN	IPM Lea		
				IPM Lea	County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4039' GR						
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF IN	TENTION TO	icate Ivatu	re of Notice, R	ceport or Other	Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK	PLUG AND ABANDON	R	EMEDIAL WORK		ALTERING CASING X	
TEMPORARILY ABANDON	N CHANGE PLANS COMMENCE DRIL			LING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB			
OTHER:						
4		O	THER: Perforate	, acidize and frac	X	
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent details, and give pertinent details, and give pertinent details.)						
starting any proposed work). SEE RULE 1103. For Multiple Completions. Attach wellhore diagram of proposed completion or						
recompliation.						
4/16/01 – Run GR/CBL. TOC at 5020'.						
4/30/01 – TIH with bit and scraper. Tag PBTD at 13.650'.						
5/1/01 - TIH with TCP installation to perforate Morrow 13 162'-13 168' 42 holes 42" holes. Drop har and						
defondie guns. Pull ICP guns,						
5/2/01 – Perforate Morrow 13,126-13,138', 78 holes, .42" holes.						
3/3/01 - Straddle perts 13,162-	·13,168'. Spotted 250 i	aals 7.5% le	HCI Break	down parfe with	1.1/2 bble in	
5/3/01 – Straddle perfs 13,162-13,168'. Spotted 250 gals 7.5% IC HCL. Breakdown perfs with 1-1/2 bbls in formation. Communicated through top perfs. Moved packer above all perfs, put acid away. Spotted 250 gals 7.5% IC HCL.						
7.070 IC LICE.						
5/4 - 5/15 - Swab and flow tes	Signature of the second of the	Π.				
5/17 = 5/25 Flourback for	5/16/01 – Frac Morrow perfs 13,126-13,168' with 68,370 gals 40# 70Q foam and 65,000# 20/40 Interprop. 5/17 – 5/25 – Flow back frac.					
5/28/01 - Rig down unit. Turn well to production. WORL						
5/28/01 – Rig down unit. Turn well to production. WOPL.						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE Mora Herper TITLE Engineering Technician DATE September 21, 2001						
Type or print name Susan Hernin						
Type or print name Susan Heri	/		· · · · · · · · · · · · · · · · · · ·			
Type or print name Susan Her (This space for State use)	/			Telephone 1	No. 505-748-1471	
(This space for State use)	/	<u>.</u>		Telephone I	No. 505-748-1471	
	/ pin	CITLE		Telephone 1		