Submit 3 copies to Appropriate

State of New Me DISTRICT I Energy, Minerals and Natural Re		
P.O. Box 1980, Hobbs NM 88240		VELL API'NO.
P.O. Drawer DD, Artesia NM 38210 P.O. Box 20	88	30-025-35098
DISTRICT III Santa Fe, New Mexico 87	/504-2088	i. Indicate Type of Lease State
1000 Rie Brazos Rd., Aztec NM 87410		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO D DIFFERENT RESERVOIR. USE "APPLICATION FOR (FORM C-101) FOR SUCH PROPOSALS.)		Lease Name or Unit Agreement Name VO-4715
1. Type of Well: OIL GAS WELL WELL WELL		Rock Ridge AWD State
2. Name of Operator Yates Petroleum Corporation		i. Well No. 1
3. Address of Operator 105 South 4th., Artesia, NM). Pool Name or Wildcat Wildcat Morrow
4. Weil Location Unit Letter F : 1800 Feet From The North	Line and 1980 Feet	From The West Line
Section 10 Township T15S Range R35E	NMPM	Lea COUNTY
10. Elevation (Show whether DF, RKB, 4166' GR	RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of No	tice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS		PORT OF: ALTERING CASING
	CASING TEST AND CEMENT JOB	
	OTHER Production casing	
	THER Production casing rtient details, and give pertinenet dat 10-01. TOH for logs - SLM. Lo 5 jts (13,950.48') casing, set (ttom of marker set @ 9692'. T 5#/sx LCM + .8% FL-25 + .4 + 3#/ sx LCM-1 (yld 1.94, wt	ogs on bottom @ 7:20 pm @ 13,930' as follows: ⁻ op of marker set @ % FL-52 + .4%.
OTHER 12. Describe Proposed or Completed Operations (<i>Clearly state all pedate of starting any proposed work</i>) SEE RULE 1103. 1-10-01- Circulate for logs. TD 7-7/8: hole @ 1:30 am 1- 1-12-01- Circulate to run 5-1/2" casing. 1-13-01- Rigged up & ran 5-1/2" casing. 1-14-01- Set slips. Cut off 5-1/2" casing. Rig up & run 33 47 jt 5-1/2" 20# M/P110 blasted (1939.76') 47 jts 5-1/2" 17# M/P110 blasted (1959.29') 9 jts 5-1/2" 17# N-80 blasted (359.76') 196 jts 5-1/2" 17# M/P110 varn (1478.21') Float shoe set @ 13,930'. Float collar set @ 13,888'. Bo 9672'. Stage 1: Cemented w/ 1145 sx 15:16:11 POZ C + Stage 2: cemented w/ 980 sx 35:65:6% gel + .5% FL-52 100 sx "H" + .3% FL-52 (yld 1.18, wt 15.6). PD @ 12:30	OTHER Production casing rtient details, and give pertinenet dat 10-01. TOH for logs - SLM. Lo 5 jts (13,950.48') casing, set (ttom of marker set @ 9692'. T • 5#/sx LCM + .8% FL-25 + .4 + 3#/ sx LCM-1 (yld 1.94, wt pm 1-14-01.	ogs on bottom @ 7:20 pm @ 13,930' as follows: [*] op of marker set @ % FL-52 + .4%. 12.5). Tailed in with
OTHER 12. Describe Proposed or Completed Operations (Clearly state all perdate of starting any proposed work) SEE RULE 1103. 1-10-01- Circulate for logs. TD 7-7/8: hole @ 1:30 am 1- 1-12-01- Circulate to run 5-1/2" casing. 1-13-01- Rigged up & ran 5-1/2" casing. 1-14-01- Set slips. Cut off 5-1/2" casing. Rig up & run 33 47 jt 5-1/2" 20# M/P110 blasted (1939.76') 47 jts 5-1/2" 17# M/P110 blasted (1959.29') 9 jts 5-1/2" 17# N-80 blasted (359.76') 196 jts 5-1/2" 17# M/P110 varn (1478.21') Float shoe set @ 13,930'. Float collar set @ 13,888'. Bo 9672'. Stage 1: Cemented w/ 1145 sx 15:16:11 POZ C + Stage 2: cemented w/ 980 sx 35:65:6% gel + .5% FL-52 100 sx "H" + .3% FL-52 (yld 1.18, wt 15.6). PD @ 12:30 Rig released @ 8:30 am 1-14-01.	OTHER Production casing rtient details, and give pertinenet dat 10-01. TOH for logs - SLM. Lo 5 jts (13,950.48') casing, set (5 jts (13,950.48') casing, set (5 st/sx LCM + .8% FL-25 + .4 + 3#/ sx LCM-1 (yld 1.94, wt pm 1-14-01.	ogs on bottom @ 7:20 pm @ 13,930' as follows: [*] op of marker set @ % FL-52 + .4%. 12.5). Tailed in with
OTHER 12. Describe Proposed or Completed Operations (Clearly state all perdate of starting any proposed work) SEE RULE 1103. 1-10-01- Circulate for logs. TD 7-7/8: hole @ 1:30 am 1- 1-12-01- Circulate to run 5-1/2" casing. 1-13-01- Rigged up & ran 5-1/2" casing. 1-14-01- Set slips. Cut off 5-1/2" casing. Rig up & run 33 47 jt 5-1/2" 20# M/P110 blasted (1939.76') 47 jts 5-1/2" 17# M/P110 blasted (1959.29') 9 jts 5-1/2" 17# N-80 blasted (359.76') 196 jts 5-1/2" 17# M/P110 varn (1478.21') Float shoe set @ 13,930'. Float collar set @ 13,888'. Bo 9672'. Stage 1: Cemented w/ 1145 sx 15:16:11 POZ C + Stage 2: cemented w/ 980 sx 35:65:6% gel + .5% FL-52 100 sx "H" + .3% FL-52 (yld 1.18, wt 15.6). PD @ 12:30 Rig released @ 8:30 am 1-14-01. Interest certify that the information above a true and completered the best of my knowledge and beliets SIGNATURE Donna Clack TYPE CR PRINT NAME Donna Clack	отнея <u>Production casing</u> rtient details, and give pertinenet dat 10-01. TOH for logs - SLM. Lo 5 jts (13,950.48') casing, set (5 jts (1	ogs on bottom @ 7:20 pm @ 13,930' as follows: ^c op of marker set @ % FL-52 + .4%. 12.5). Tailed in with <u>ctian DATE 1/15/02</u> <u>тецерноме мо 505-748-1471</u> FEB 0 4 2002
OTHER 12. Describe Proposed or Completed Operations (Clearly state all period date of starting any proposed work) SEE RULE 1103. 1-10-01- Circulate for logs. TD 7-7/8: hole @ 1:30 am 1- 1-12-01- Circulate to run 5-1/2" casing. 1-13-01- Rigged up & ran 5-1/2" casing. 1-14-01- Set slips. Cut off 5-1/2" casing. Rig up & run 33 47 jt 5-1/2" 20# M/P110 blasted (1939.76') 47 jts 5-1/2" 17# M/P110 blasted (1959.29') 9 jts 5-1/2" 17# N-80 blasted (359.76') 196 jts 5-1/2" 17# N-80 blasted (359.76') 196 jts 5-1/2" 17# M/P110 varn (1478.21') Float shoe set @ 13,930'. Float collar set @ 13,888'. Bo 9672'. Stage 1: Cemented w/ 1145 sx 15:16:11 POZ C + Stage 2: cemented w/ 980 sx 35:65:6% gel + .5% FL-52 100 sx "H" + .3% FL-52 (yld 1.18, wt 15.6). PD @ 12:30 Rig released @ 8:30 am 1-14-01. I hereby certify that the information above a true and completerso the best of my knowledge and belt SIGNATURE TYPE CR PRINT NAME Donna Clack TITLE	OTHER Production casing rtient details, and give pertinenet dat 10-01. TOH for logs - SLM. Lo 5 jts (13,950.48') casing, set (5 jts (13,	ogs on bottom @ 7:20 pm @ 13,930' as follows: ^c op of marker set @ % FL-52 + .4%. 12.5). Tailed in with <u>cian DATE 1/15/02</u> <u>тецерноме NO 505-748-1471</u>