

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-35109

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

7. Lease Name or Unit Agreement Name

GREEN STAR "22" STATE

8. Well No.

1

9. Pool Name or Wildcat

ANDERSON RANCH WOLFCAMP

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER NEW WELL ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter G : 1980 Feet From The NORTH Line and 2310 Feet From The EAST Line
Section 22 Township 16-S Range 32-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4312'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☒

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

COMPLETION REPORT ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-17-00/10-23-00: NO ACTIVITY.

10-24-00: NUBOP. UNLOAD & TALLY 351 JTS 2.875" 6.5 L80 TBG. MAKE UP 4.750' VAREL BIT, BIT SUB, PU DC'S & TIH,

10-25-00: TAG DV TOOL @ 8901'. DRILL OUT DV TOOL. DISPL HLE W/2% KCL.

10-26-00: RAN GR/CCL LOG FR 9915-8877. PERF WOLFCAMP FR 9752-9767', 15', 60 HLS 4 JSPF. 120 DEG PHASING. TIH W/PKR & 2 7/8" TBG. LEFT SWING ABOVE PERFS.

10-29-00: SPOT 100 GALS 15% HCL, PERFS 9752-9767. TOH TO 9645. SET PKR. TP @ 9706. NDBOP. NUTREE. TEST TO 2500 PSI. NU TREE SAVER. TEST TO 9000 PSI. ACIDIZED WOLFCAMP PERFS W/1500 GALS 15% HCL & 90 1.1 BALL SEALER. NDTREE SAVER. FLOWBACK.

10-30-00: SWABBING.

11-04-00: MIRUSU. NDTREE. NUBOPS. PU ON TBG & REL ON-OFF TOOL. WELL FLOWING.

11-05-00: UNLOAD & TALLY 3.5" TBG.

11-07-00: RU KILL TRUCK. PUMP 50 BBLS BRINE DN TBG. WELL DEAD. REL ON-OFF TOOL.

11-09-00: TIH W/250 JTS 3.5" TBG. LATCH ON PKR & TEST TO 2500 PSI.

11-10-00: NU FRAC TREE. TEST ANNULUS TO 2500 PSI.

11-11-00: TEST LINES TO 8700. PUT 2500 ON ANNULUS. PERFS 9752-9767. PKR @ 9645. TP @ 9706. ACID FRAC W/2000 GALS WF130, 5000 GALS 15% HCL, 4000 GALS WF130, 5000 GALS 15% HCL, 4000 GALS WF130, 5000 GALS 15% HCL, 4000 GALS WF130, 5000 GALS 15% HCL. FLSH TO BTM PERF W/90 BBLS WF130.

11-14-00: FLOWING. SWABBING.

11-17-00: NDTREE. NUBOPS. LD 3.5" TBG. CHANGE 3.5" RAMS TO 2.375" RAMS. PUMP 2% KCL DN ANNULUS. TOH W/PKR & TBG.

11-21-00: TIH W/PURGE VALVE, MD JT, SN, TA & 2 7/8" TBG. RIG REL @ 1730 HRS 11/20/00. SN @ 9804.52'

11-22-00: INSTL PUMPING UNIT.

11-29-00: MIRUSU. TIH W/PUMP & ON/OFF TOOL & RDS. RIG DOWN SU 11-30-00.

WILL SEND IN FINAL PUMP TEST WHEN AVAILABLE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 12/4/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____ DATE _____