Submit 3 Copies To Appropriate District       State of New Mexico       Form C         Office       Energy, Minerals and Natural Resources       Revised March 23         District I       OIL CONSERVATION DIVISION       30-025-35477         811 South First, Artesia, NM 88210       OIL CONSERVATION DIVISION       30-025-35477         District III       2040 South Pacheco       STATE       FEE	C-103
District I       Energy, Minerals and Natural Resources       Revised Match 2.         1625 N. French Dr., Hobbs, NM 88240       District II       0IL CONSERVATION DIVISION       30-025-35477       35/172         811 South First, Artesia, NM 88210       OIL CONSERVATION DIVISION       5. Indicate Type of Lease	
I625 N. French Dr., Hobbs, NM 88240WELL API NODistrict II0IL CONSERVATION DIVISION811 South First, Artesia, NM 882102040 South PachecoDistrict III2040 South Pacheco	5, 1999
811 South First, Artesia, NM 88210       OIL CONSERVATION DIVISION       5. Indicate Type of Lease         District III       2040 South Pacheco       5. Indicate Type of Lease	
District III 2040 South Pacheco	
	1
District III2040 South Facilities1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505District IV6. State Oil & Gas Lease No.	
2040 South Pacheco, Santa Fe, NM 87505 26643	
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement N	lame:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Lord Baltimore "20" State	
PROPOSALS.) 1. Type of Well:	
Oil Well 🗹 Gas Well 🗆 Other	
2. Name of Operator8. Well No.	
David H. Arrington Oil & Gas, Inc	
3. Address of Operator 9. Pool name or Wildcat	
P.O. Box 2071, Midland, Texas 79702 Wildcat Wolfcamp	
4. Well Location	
Unit Letter K_: 1400' feet from the South line and 1460' feet from the West line	ne
Section 20 Township 16S Range 35E NMPM County Le	a
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	
4020' GR	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK ALTERING CASI	NG 🗖
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND	. 🗆
PULL OR ALTER CASING	
COMPLETION CEMENT JOB	
OTHER OTHER Complete Drlg & Set Production Casing	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimate	d date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed compl or recompilation.	letion
5/8/01- Drilled 7 7/8" hole to TD @ 11,275'. Circ for DST #3.	
5/9/01- TIH to bottom of casing @ 4750'. Finish DST #3. RU manifold & lines.	
5/10-13/01- Logging.	arou/
5/14/01- RD loggers, TIH w/DC's, cut drilling line, circ to run casing, LD DS & pull casing wear ring & RU casing of 5/15/01- RD - 5/12/20 sys HCl - Plug down @ 18:15	nlug
5/15/01- Ran 5 <sup>1</sup> / <sub>2</sub> " casing to 11,275' & cement w/lead 340 sxs Prem HCl & tail w/250 sxs HCl. Plug down @ 18:15 held. ND, set slips & BOP. NU tbg head & test to 5000 psi, ok. Finish cleaning pit, RD & release rig @ 04	, plug 100
neiu. IND, set sups & DOF. NO tug neau & test to 5000 psi, ok. Finish cleaning pit, KD & release ng @ 0-	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.         SIGNATURE	
SIGNATURE DATE DATE6/11/01_	
SIGNATURE	
SIGNATURE	
SIGNATURE       DATE_6/11/01_         Type or print name       Chuck Sledge         Type or print name       Chuck Sledge	

7

.