DISTRICT I

State of New Mexico Energy, Minerals and Natural Resources Department

P.O. Box 1980, Hobbs NM 88240			WELL API NO	
DISTRICT II	OIL CONSERVA		20 205 25252	
P.O. Drawer DD, Artesia NM 88210	P.O. Bo Santa Fe, New Mexic		30-025-35250	
DISTRICT III 1000 Rio Brazos Rd., Aztec NM 87410	Santa i e, ivew iviexi	50 07504-2000	5. Indicate Type of Lease State FEE	
	CES AND REPORTS ON WELLS		State 1	
DIFFERENT RE	FOR PROPOSALS TO DRILL OR ESERVOIR. USE " APPLICATION 1) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name	
OIL GAS WELL WELL X O	THER		Chevy AWV State Co	
2. Name of Operator Yates	Petroleum Corporation	 n	a. Well No.	
3. Address or Operator 105 South 4th., Artesia, NM 88210			9. Pool Name or Wildcat Eidson Morrow, North	
Unit Letter N : 1100 Fe	eet From The South	Line and 1600	Feet From The West Lie	
Section 13 Township T	T15S Range R34E	NMPM	Lea COUNT	
10. Elev	ation (Show whether DF, R	RKB, RT, GR, etc.)		
	4056' GR	,		
 Check Appropriate B 	Box to Indicate Nature of	Notice, Report, or Other D	pata	
NOTICE OF INTENTION		1	ENT REPORT OF:	
	LUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON C	HANGE PLANS	COMMENCE DRIVING ORGA		
	TANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONME VT	
PULL OR ALTER CASING	_	CASING TEST AND CEMENT JOB		
OTHER		OTHER COMPLETION		
Displace hole w/ 7% KCL w/ 9 12-19-01- RU wireline. Log G	d tubing. Tagged @ 726 ement stringers from 74 ent. Clean out to liner tops. Tag top of liner @ 943 Tagged liner top. Tagged surfactants. TOH - SI. SR CBL from PBTD to tong guns loaded 6 JSPF	67'. RU swivel & drill cements. 15-8636'. Drilled to 8700'. 60. Tag tubing @ 9436'. Circ 8'. Drilled 9' of cement & fell I PBTD. Pickle tubing w/ 10 pp of liner @ 9410'. TOH. Perforated middle Morrow	t to 7415'. Circ clean. Circ clean. SI. clean. thru. TIH & tagged PBTD 9 107; 00 gal 15% HCL. Reverse out.	
RD wireline. TIH w/ packer. F 12-21-01- Rig up swab; relea Shut in.	sed packer. ND tree & f	NU BOP. TOH. Set 4-1/2" (CIBP @ 12960'. Cap w/ 10' cement	
RD wireline. TIH w/ packer. F 12-21-01- Rig up swab; relea Shut in. 12-21-01- RU wireline. Shot u	sed packer. ND tree & f	NU BOP. TOH. Set 4-1/2" (CIBP @ 12960'. Cap w/ 10' cement ্ডিই <u>এ</u> হ ৮ে	
RD wireline. TIH w/ packer. F 12-21-01- Rig up swab; relea Shut in. 12-21-01- RU wireline. Shot u 12-24-01- Turned well to proceed the company of the compan	sed packer. ND tree & f	NU BOP. TOH. Set 4-1/2" (CIBP @ 12960'. Cap w/ 10' cement	
RD wireline. TIH w/ packer. F 12-21-01- Rig up swab; relea Shut in. 12-21-01- RU wireline. Shot u 12-24-01- Turned well to produce a ruse and bischature	sed packer. ND tree & f	NU BOP. TOH. Set 4-1/2" C	CIBP @ 12960'. Cap w/ 10' cement	

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER