Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240	C.		WELL API NO.
District II	OIL CONSERVATION DIVISION		30-025-35616
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa PC, 14141 67303		6. State Oil & Gas Lease No.
87505		28297	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			T IT
PROPOSALS.)			Lou's Hopper
1. Type of Well:			
Oil Well Gas Well Other			5 Y 11 Y
2. Name of Operator		7. Well No.	
David H. Arrington Oil & Gas, Inc		8. Pool name or Wildcat	
3. Address of Operator		Wildcat Mississippian	
P.O. Box 2071, Midland, Texas 79703 Wildcat Mississippian Wildcat Mississippian			
4. Well Location B			
Unit Letter Ø	: 660' feet from theNort	h line and1	980'feet from theEastline
Section 19	Township 15S	Range 35E	NMPM Lea County
	10. Elevation (Show whether	DR, RKB, RT, GR, et	<i>c.)</i>
11 Ch - 1-	4030' GR	Noture of Notice	Report or Other Data
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK		REMEDIAL WOR	
PERFORM REMEDIAL WORK L	1 PEUG AND ABANDON L	(CINESIAE TO	, , , , , , , , , , , , , , , , , , , ,
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS. PLUG AND
_] — []	CACING TEST A	ND ABANDONMENT ABANDONMENT
PULL OR ALTER CASING L	MULTIPLE COMPLETION	CASING TEST A	sdoot 11
	COM EL HOIT		771,
OTHER:			, Set Surface & Intermediate Casing
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompilation.			
1/9/02- MIRU JW Drilling rig #3. Spud 17 1/2" hole and drill to 509'. Ran 13 3/8" casing 48# & set at 509'. Circ & cement casing			
with 525 sxs Prem Plus with 2% CaCl2. Circ 96 sxs. Wait on cement. Cut off casing & weld on head & test to 600 psi- ok.			
NIL stack Test blind rams to 500 psi-ok. Test pipe rams, shoe & casing to 500 psi-ok.			
1/26/01- Drill 11" hole to 5980'. Ran 8 5/8" casing 32# & set at 5980'. Circ & cement casing with Lead-1665 sxs 1/4# sk Flocele			
Interfill "C" & Interfill "C" Neat & Tail-250 sxs 1% CaCl2 Pos Plus. Circ 290 sxs. ND & set slips. NU stack.			
1/27/01-Drill cement & plug. Test BOP's & casing to 1500 psi-ok. Resume drilling.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
I hereby certify that the informati	on above is true and complete to	ine best of my knowle	age and coner.
SIGNATURE /	Sh/TITI	EEngineer	DATE1/28/02
Type or print name Chuck Sledge Telephone No. (915) 682-6685			
(This space for State use)		t	·
Laboration DIV	ORIGINAL SIGNED BYITL	я — — — — — — — — — — — — — — — — — — —	DATE
APPPROVED BY	PAUL F. KAUTZ	PETROLEUM	FAIOURS 1:
Conditions of approval, it ally.	PETROLEUM ENGINEER	4 FILIUTEON	FEB 0 5 2002