

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

FORM C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30025-35635
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Injection <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Concho Oil & Gas Corp.		6. State Oil & Gas Lease No.
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701		7. Lease Name or Unit Agreement Name: Big D State
4. Well Location Unit Letter <u>11</u> : <u>3498</u> Feet from the <u>North</u> line and <u>1200</u> feet from the <u>East</u> line Section <u>6</u> Township <u>16S</u> Range <u>34E</u> NMPM Lea County		7. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4164GR		8. Pool name or Wildcat Morrow Strawn

CONFIDENTIAL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Plug & Abandon wellbore <input checked="" type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Concho Oil & Gas Corp. has plugged and abandoned the Big D State No. 1 well according to the following procedure:

03-09-02 Set 35 sx H plug @ 12,601' - 12,500'.
Set 35 sx H plug @ 10,425' - 10,825'.
Set 35 sx H plug @ 7,965' - 7,865'.
Set 35 sx H plug @ 5,960' - 5,860'.
Set 40 sx C plug @ 4,579' - 4,443'. Tag cmt @ 4443'
Set 35 sx C plug @ 1,580' - 1,480'.
Set 115 sx C plug @ 453' - Surface.
Set 10 sx C plug @ Surface plug.
Cut off wellhead & clean location. Release rig @ 12:30 PM.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathem TITLE Production Analyst DATE 3-11-02

Type or print name Terri Stathem Telephone No. 915/683-7443

(This space for State use)

APPROVED BY Steve Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JAN 16 2003

Conditions of approval, if any