Form 3160-5 November 1983) Formerly 9-331) DEPARTMEN: OF THE INTERIOR (Other instructions werse side) BUREAU OF LAND MANAGEMENT	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	N.M. 6863 6. IF INDIAN, ALLOTTER OR TRIBE NAME
OIL X GAS WELL OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
MEWBOURNE OIL COMPANY	ANADARKO FED
3. ADDRESS OF OPERATOR	9. WBLL NO.
P.O. BOX 5270 - HOBBS, NEW MEXICO 88241	1
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 	10. FIELD AND POOL, OR WILDCAT
66c/8 1198c/a	11. BBC, T., R., M., OB BLK, AND SURVEY OF AREA SOC 27 T-18S R-32E
14. PERMIT NO. 15 ELEVATIONS (Show whather no per constant	UNIT LETTER N 660 FSL 1980 FWL
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	I.F.A N.M.
Check Appropriate Box to Indicate Nature of Notice, Keport, o	
don't	REQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETS	REPAIRING WELL
PRACTICE TELETIMENT	ARANDONMENTS X
SHOUTING OR ACIDIZING	ABANDONMENT* A
(Nors: Report res	uits of multiple completion on Well upletion Report and Log form.)
1. SET 9 5/8 CIBP AT 3650' 2. SPOT 15 SKS CEMENT ON TOP OF 9 5/8 CIBP 3. LOAD HOLE W/MUD 4. SPOT 45 SKS CEMENT AT 805' WOC TACCED PLUG AT 650' 5. SPOT 20 SKS CEMENT FROM 64 ft. TO SURFACE 0 SET P&A MARKER.	
18. I hereby certify that the foregoing is true and correct PEA SUPERVISOR	7.05.01
(This space for Federal or State office use)	DATE
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE 9/27/91