

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP DATE
(Other instructor re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

REVISED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME Querecho Plains Unit
2. NAME OF OPERATOR Shell Oil Company (Western Division)	8. FARM OR LEASE NAME Querecho Plains Unit
3. ADDRESS OF OPERATOR Post Office Box 1509, Midland, Texas 79701	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1980' FWL (SW/4 SW/4) Section 27, T-18-S, R-32-E, NMPM Survey, Lea County, New Mexico	10. FIELD AND POOL, OR WILDCAT Querecho Plains (Bone Springs)
14. PERMIT NO. --	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 27, T-18-S, R-32-E, NMPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3735' DF	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☒(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pulled rods.
2. Spotted 150' minimum (25 sacks) cement plug 8450'-8600' over Bone Springs.
3. Pulled pump and tubing.
4. Set CIBP at 6400' and capped with 1 sack cement.
5. Treated with 300 gallons 15% NEA (6360'-6000').
6. Pulled tubing and perforated Delaware with 1 - 3/8" jet shot at 6254', 6256', 6270', 6272', and 6277' (5 holes).
7. Ran FB packer on 2 1/2" tubing and set at 6113'.
8. Fraced via tubing as follows:
 - A. Pumped 500 gallons LO containing 25# Adomite Mark II.
 - B. Pumped 2000 gallons LO containing 100# Adomite Mark II + 1#/gallon 20-40 mesh sand.
9. Swabbed.
10. Pulled tubing and packer.
11. In 24 hours pumped 16 BW, no oil. Operation to recomplete in Delaware sand unsuccessful.

18. I hereby certify that the foregoing is true and correct

ORIGINAL
SIGNED BY D. L. Lilly TITLE Division Mechanical Engineer DATE September 27, 1967

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.