

ATTACHMENT TO EXHIBIT #1
Notes Regarding the Blowout Preventers
Lusk Deep Unit "A" #3
Lea County, New Mexico

1. Blowout preventer and all related equipment and fittings must be in good working condition and be 3000 PSI W.P. minimum.
3. The blowout preventer control is to be located as close to the driller's position as feasible.
4. The blowout preventer closing equipment will be manual.
5. Hand wheels are to be properly installed and operable.
6. A safety valve, in full open position, must be readily available on the rig floor at all times with the proper pipe threads. This valve is to be full bore and 3000# W.P. minimum.