

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 8-5310	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Cities Service Oil Company	8. Farm or Lease Name Ohio A-State
3. Address of Operator Box 69 - Hobbs, New Mexico	9. Well No. 6
4. Location of Well UNIT LETTER H 2310 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 17S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Corbin Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4051 GR	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandon the above well in the following manner:

1. Set a CI bridge plug in 7" csg. @ 3700 (7" set @ 3735 w/50 sacks)
2. Dump a 2 sack cement plug on top of bridge plug.
3. Cut and pull approx. 2500' of 7" casing.
4. Set a 50 sack cement plug @ 2350-2650 (½ in and ½ out of 7" csg stub @ 2500).
5. Set a 50 sack cement plug @ 1300-1425 (½ in and ½ out of 8 5/8" csg set @ 1368' w/100 sacks).
6. Set a 10 sack cement surface plug @ 0-30' w/4" dry hole marker.
7. Clean location of all debris and equipment.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____

TITLE **District Admin. Supervisor**

DATE **5/28/70**

APPROVED BY

Lester A. Clements

TITLE

Oil & Gas Inspector

DATE

JUN 1 1970

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 1 1970

**OIL CONSERVATION COMM.
HOBBS, N. M.**