NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by Checking B	elow
Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper
Notice of Intention to Plug Well	Notice of Intention to Plug Back	Notice of Intention to Set Liner
Notice of Intention to Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)
Notice of Intention to Gun Perforate	Notice of Intention (Other) Test Queen Section	Notice of Intention (Other)
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO	Midland, Texas	February 7, 1962
Gentlemen:		
		1 P
(Company or Operator) State r	Well NolinF(Unit)
SE 1/4 NN 1/4 of Sec. 36	, T, R33,NMPM	.,
Lea Cor	anty.	
(FOLLOW	INSTRUCTIONS IN THE RULES AND	OF WORK REGULATIONS)
erforate, acidize with 500 g erforate, acidize with 500 g erforate, acidize with 500 g	als, and test 4106-4116 als, and test 3974-3984	REGULATIONS)
erforate, acidize with 500 g erforate, acidize with 500 g erforate, acidize with 500 g	als, and test 4106-4116 als, and test 3974-3984 als, and test 3912-3922	REGULATIONS)
erforate, acidize with 500 g erforate, acidize with 500 g erforate, acidize with 500 g	als, and test 4106-4116 als, and test 3974-3984 als, and test 3912-3922	REGULATIONS)
erforate, acidize with 500 g erforate, acidize with 500 g erforate, acidize with 500 g	als, and test 4106-4116 als, and test 3974-3984 als, and test 3912-3922	REGULATIONS)
erforate, acidize with 500 g erforate, acidize with 500 g erforate, acidize with 500 g erforate, acidize with 1000	als, and test 4106-4116 als, and test 3974-3984 als, and test 3912-3922 gals and frac with 5000 gal o	REGULATIONS)
erforate, acidize with 500 g erforate, acidize with 500 g erforate, acidize with 500 g erforate, acidize with 1000 Approved	als, and test 4106-4116 als, and test 3974-3984 als, and test 3912-3922 gals and frac with 5000 gal o Texas By Position	REGULATIONS) 11 3843-3870 Gull Producing Company
erforate, acidize with 500 g erforate, acidize with 500 g erforate, acidize with 500 g erforate, acidize with 1000	als, and test 4106-4116 als, and test 3974-3984 als, and test 3912-3922 gals and frac with 5000 gal o Texas By Position Dist. Send	il 3843-3870 Gulf Producing Company Company or Obstace Prod. Superintendent