

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.

30-025-01507

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-2148

7. Lease Name or Unit Agreement Name

Caprock Maljamar Unit

8. Well No.

59

9. Pool name or Wildcat

Maljamar Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL ☐

GAS ☐

WELL ☐

WELL ☐

OTHER

P & A

2. Name of Operator

The Wiser Oil Company

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico (505) 392-9797

4. Well Location

Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line

Section 21 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4180' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

02/29/00 MIRU Mayo Marrs Casing Pulling Inc. NU BOP. Lined pit per OCD. Bled down water.

03/01/00 Flowed well down. Unseat pkr. LD 69 jts. RIH & set CIBP @ 4260'. RIH w/2-3/8" tbg. Circulated 10# mud. Spotted 25 sks. @ 4260'-4060'.
POH. Perforated @ 2325'. RIH w/pkr. Tested to 1800'. Confered w/OCD. Closed in well.

03/02/00 RIH w/2-3/8" tbg. Spotted 25 sks. @ 2375'-2075'. POH. Perforated @ 1500'. RIH w/pkr. to 1000'. Squeezed 40 sks. Closed in @ 800#.

03/03/00 RIH & tagged @ 1378'. POH. Perforated @ 400'. Set pkr. @ 60'. Squeezed 163 sks. to surface. Released pkr. Spotted 10 sks. @ 60' to surface.
(Required by Johnny Robinson & Gary Wink w/NMOCD) RD. Cut off WH & anchors. Covered pit & cellar. Install dry hole marker. Well is P & A.
Final Report.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner
TYPE OR PRINT NAME Mary Jo Turner

TITLE Completion Department

DATE June 20, 2000

TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

DATE

Jo - GWW