

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Grande Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-01516
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2148
7. Lease Name or Unit Agreement Name Leamex
8. Well No. 7
9. Pool name or Wildcat Leamex Penn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, Texas 79762	
4. Well Location Unit Letter <u>F</u> : <u>1976</u> Feet From The <u>West</u> Line and <u>1980</u> Feet From The <u>North</u> Line Section <u>23</u> Township <u>17-S</u> Range <u>33-E</u> NMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DP, RKB, RT, CR, etc.) 4150' RKB, 4137' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Squeeze Upper Penn Perfs ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/13/92: RU DDU. COOH w/rods. NU BOP - COOH w/tbg.
5-15-92: Set plug. 11000 feet - test to 500 psi (held). Set packer at 10400. Drop 2 sacks of sand on plug. COOH - L/D packer. GIH w/retainer - to 10,000 feet.
5-18-92: Run retainer 10500 feet. Pump 34 bbls fresh water load tbg. Pump 200 sxs. Thick set. Pump 100 sxs Class H. Squeeze at 2000#. Last 100 sxs of Class H. WOC.
5-19-92: GIH w/tbg. Drlg 10' of cement and retainer. Circ. hole clean.
5-20-92: GIH - Drlg out retainer - 10511. Drlg out cement to 10724. Circ hole clean. COOH 100'.
5-21-92: Drlg out cement. Test to 500#. Circ. sand off of plug. COOH w/tbg. LD collars and bit.
5-22-92: GIH w/tbg. Retrieve RBP and COOH. L/D plug.
5-26-92: GIH w/tbg and rods. 5-27-92: Hang well on - start pumping. (Over)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv., Reg. & Proration DATE 06-16-92

TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. (915) 368-1488

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

6-16-92: Test 24 oil, 75 wtr., 75 gas.

RECEIVED

JUN 17 1992

JOHN HOBBS OFFICE