

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

ORDER OTHER RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

API No. 30-025-01516

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER ☐	3a. Indicate Type of Lease State ☒ Fee ☐
Name of Operator Phillips Petroleum Company			3. State Oil & Gas Lease No. B-2148
Address of Operator Room 401, 4001 Penbrook, Odessa, TX 79762			7. Unit Agreement Name ---
Location of Well UNIT LETTER <u>F</u> 1976 FEET FROM THE <u>west</u> LINE AND <u>1980</u> FEET FROM THE <u>north</u> LINE, SECTION <u>23</u> TOWNSHIP <u>17-S</u> RANGE <u>33-E</u> N.M.P.M.			8. Farm or Lease Name Leamex <i>Buy 2</i>
			9. Well No. 7
			10. Field and Pool, or Wildcat Leamex (Penn)
15. Elevation (Show whether DF, RT, GR, etc.) 4148' DF			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
RE-DRILL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒	ALTERING CASING ☐
COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
CASING-TEST AND CEMENT JOBS ☐	OTHER <u>add perforation in Penn. zone</u> ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

- 18-83: Rng 2-3/8" tbg w/overshot to fish 4" csg gun. Well units WSU installed BOP. Pld 1" and 2" tbg, KOBE BHA & Baker Seal assembly. Tom Hansen Co. ran gauge ring to 7000'. Ran 4" csg gun and stuck @ 11,000', pld out of rope socket. Started in hole w/overshot, jars and sub.
- 19-83: Running tbg. Finished rng tbg, caught top of 4-1/2" perf gun. Jarred on fish 4 hrs, unable to pull free. Released overshot pld tbg, jars, bumper sub and overshot. Started in hole w/overshot, jars, sub, 4--3-1/2" DC's and 2-3/8" tbg.
- 20-83: Caught top of fish @ 11,000'. Pld off of fish, could not re-catch, POOH changed overshot. Ran overshot jars and subs, DC's & 50 jts of 2-3/8" tbg.
- 21,22 3-83: 21st, SD. Ran 2-3/8" tbg caught top of fish. Jarred 4 hrs, pld fish free. COOH, LD Tom Hansen 4" csg gun. 22nd, 23rd, dwn 48 hrs -- crew off.
- 24-83: Prep to drill on Baker Model D pkr. Ran 4-5/8" shoe w/4--3-1/2" DC's and 2-3/8" tbg. Drld on pkr 2 hrs using 110 BW. Ran out of water. Pld shoe to 10,000. Filled pits and SDON.

SEE REVERSE SIDE

OP Equip: Series 900, 3000# WP, double w/1 set pipe rams, 1 set blind rams, manually operated.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

[Signature] W. J. Mueller TITLE Sr. Engineering Specialist DATE March 2, 1983

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

TITLE

DATE MAR 9 1983

NEXT PAGE

1-25-83: Dredged 3 hrs, freed pkr. Lowered tbg and shoe to 11,350'. Circled hole clean. 7' tbg, LD DC's and shoe. MO reverse unit.

1-26-83: Tom Hansen/Art 5-4" csg w/2 JSPF from 11,248'-11,250'; 11,256'-11,271'; total of 17' w/34 holes. Ran 2-3/8" tbg w/Baker Model "R" pkr, left tbg hanging @ 11,283'.

1-27-83: Set pkr @ 11,271'. Dowell trtd as follows: Sptd 250 gals 15% NeFe HCL from 11,271'-11,003'. Reset pkr @ 10,980' and trtd csg perfis from 11,248'-11,301' w/1000 gals 15% NeFe HCL. Pmpd 150# Benzoic acid flakes and 150# rock salt in 10 bbls gelled brine followed by 1500 gals acid. Flshd w/55 bbls gelled brine. Max press 4400#, min 2750#, ISDP "0", AIR 5 BPM. Load to recover 123BLW and BAW, Swbd 5 hrs, 58 BLW and BAW.

1-28,29,30-83: 28th, swbd 10 hrs., 71 BLW. All load recovered. 30th, 31st, dwn 48 hrs--crew off.

1-31-83: Unseated pkr, pld tbg and pkr. Ran tbg anchor and KOBE BHA on 2-3/8" tbg. Set anchor at 10,598' w/tbg intake @ 10,701'.

1-1-83: Ran 1" Hydrill tbg string, stabbed into KOBE BHA @ 10,598'.

1-2-83: Filled tbg w/16 BO, circ 1 hr, lost 10 BO, press tbg to 1700# and SI. Lost pressure to 0 in 15 mins.

1-3-83: Fished standing valve and replaced w/another. Loaded tbg w/15BW press to 1500#, bled to zero in 10 mins. Dropped dummy pmp. Pmpd to seat press tbg to 1500#, bled to 0 in 5 mins.

1-4,5,6-83: 4th, pressured tbg to 1900#, dropped to 0 in 5 mins 5th, 6th dwn 48 hrs--crew off.

1-7-83: Attempted to load tbg, tbg parted. Pld 82 fts of tbg.

1-8-83: Ran overshoot on 2-3/8" tbg, caught top of fish @ 2496'. Worked 6 hrs unable to unseat anchor.

1-9-83: Dialog ran chemical cutter and cut off 2-3/8" tbg @ 10,438'. Ran overshoot, jars subs and 4-4" DC's on 55 fts of 2-3/8" tbg.

1-10-83: Finished ring 2-3/8" tbg. Caught top of fish at 10,438'. Jarred 7 hrs, unable to free anchor. Released overshoot, pld tbg, DC's, subs and overshoot.

1-11,12,13-83: 11th, SD. Ran cutrite shoe, 10 fts wash pipe, 4--3-1/2" DC's, jars and 2-3/8" tbg. Went over top of fish at 10,438'. Lowered wash pipe to 10,703'. Attempted to load hole, would not circulate. Pld up to 10,470' and started circ. Lowered shoe to 10,700' and pressured up and would not circ. Pld tbg. 12th, 13th, down 48 hrs--crew off.