

Leamex 7

Page 3

- 2-14-83: Washed over Kobe pmp cavity from 10700'-10712'.
- 2-15-83: Washed over pmp cavity from 10,712-10,717'.
- 2-16-83: Cut over Kobe cavity to 10,719', wore out shoe. POOH leaving 5 jts 4-1/8" wash pipe in hole. Started in hole w/overshot dressed to catch 2" tbg stub.
- 2-17-83: Fishing, caught fish, tripped the jars twice, freed and pld tbg & tools. Rec. 5 jts of wash and 4 1/2" shoe.
- 2-18, 19, 18th, ran 2-3/8" tbg w/1 jt wash pipe, 4-1/2" shoe, 4 DC's & jars, pmpd 550
20,21-83: BW to get circ. Drld 2'. 19th, pmpd 300 BW, unable to circ. Mixed 2 sx drift-pac, and 2 sx flocele/100 BW. Pmpd 450 bbls, did not circ. 20th, established circ, drld 2'. 21st, established circ, drld 1' - 6', shoe wore out.
- 2-22-83: Pld tbg, DC's jars & washed pipe & shoe. Changed out shoe. Ran 4--3/4" shoe, 1--4-1/2" jt of wash pipe, 4--4" DC's & 2-3/8" tbg. Drld to 10,721' in 4 hrs.
- 2-23 thru Fishing. 25th, pld 40 jts tbg.
25-83:
- 2-26,27 26th, SI. Finished pulling tbg. LD wash pipe & shoe. Ran overshot dressed
-83: to catch Kobe BHA, 4 DC's & jars. Caught fish @ 10,720', tripped jars 3 times, fish freed. POOH Rec'd 2' KOBE BHA. 27th SI 24 hrs--crew off.