

DISTRICT I

P. O. Box 1980, Hobbs, NM 88240

DISTRICT II

P. O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.

30-025-01525

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-2229

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Caprock Maljamar Unit

1 Type of Well:

OIL ☐

GAS ☐

WELL ☐

WELL ☐

OTHER

WIW

2. Name of Operator

The Wiser Oil Company

8. Well No.

98

3. Address of Operator

P.O. Box 2568 Hobbs, New Mexico

9. Pool name or Wildcat

Maljamar Grayburg San Andres

4. Well Location

Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line

Section 28 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4411' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Ran liner, perforate & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/13/99 MIRU Pool Well Service. POH w/rods & pump. ND WH RU BOP. POH w/2-7/8" tbg.

5/14/99 RU Computalog WL & ran Casing Inspection log f/ San Andres Grayburg 4128'-3100'. RD WL. RIH w/2-7/8" x 5-1/2" Arrow set pkr. & 2-7/8" tbg. Set pkr. @ 4020', 3960', 3900' & 3790'. Pressure to 250# would not hold. POH w/2-7/8" tbg. LD pkr.

5/17/99 RIH w/4-3/4" bit, sub, DC's & 2-7/8" tbg. Tag fill @ 4380'. RU reverse unit. Pump 250 bls. produced water. Drill cement f/4380'-4410'. Drill metal obstruction f/4410'-4411'. POH w/2-7/8" tbg. LD 4-3/4" bit.

5/18/99 RIH w/4-3/4" Baker drill bit, sub, DC's & 2-7/8" tbg. Tag @ 4411'. Drill on metal f/4411'-4417'. Pull above perf. interval & pump 250# crushed oyster shells. Drill to 4422'. Circulate hole clean.

5/19/99 Drilling cement f/4422'-4457'. Tag csg. shoe @ 4457'. Drill thru into formation rock to 4466'. POH w/2-7/8" tbg., DC's, sub. LD 4-3/4" Baker bit. RIH w/4-3/4" button bit, sub, DC's & 2-7/8" tbg. Tag @ 4466'. Drilling f/4466'-4527'. Circulate hole clean.

5/20/99 RIH from top of perf. interval to 4527'. Drilling formation rock. Drill f/4527'-4665'. Circulate hole clean. POH w/2-7/8" tbg. & DC's. LD sub & bit.

5/21/99 RIH w/6-1/2" Smith under rimmer sub, DC's & 2-7/8" tbg. to 4462'. Drill under rim open hole f/4462'-4617'. Circulate hole clean. Pull above perf interval.

5/22/99 RIH f/top of perf. interval to 4617'. Drill under rim to TD 4665'. POH w/2-7/8" tbg. & DC's. LD under rimmer. RIH w/4-3/4" bit, sub, DC's & tbg. to 4660'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Mary Jo Turner

TYPE OR PRINT NAME

Mary Jo Turner

TITLE

Production Tech II

DATE

November 12, 2001

TELEPHONE NO.

(505) 392-9797

(This space for State Use)

APPROVED BY

TITLE

PETROLEUM ENGINEER

DATE

JAN 11 2002