

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals & Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
1625 French Drive Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.
30-025-01535

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-2229

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Caprock Maljamar Unit

1 Type of Well:
OIL ☐ GAS ☐
WELL ☐ WELL ☐ OTHER T & A

2. Name of Operator
The Wiser Oil Company

8. Well No.
92

3. Address of Operator
P.O. Box 2568 Hobbs, New Mexico (505) 392-9797

9. Pool name or Wildcat
Maljamar Grayburg San Andres

4. Well Location
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line
Section 28 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4185' RT

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Temporary Abandon</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

01/15/98 MIRU Ram Well Service. Moved in BOP.

01/16/98 NU BOP. RIH w/5-1/2" CIBP & set @ 4140'. Circulated pkr. fluid. POH & LD tbg. ND BOP. RD unit. Well is TA'd.

01/19/98 RIH w/AD-1 pkr on 2-7/8" tbg. Tagged CIBP @ 4140'. Set AD-1 pkr. @ 4138'. Flowing out tbg. POH w/2-7/8" tbg. & AD-1 pkr. RU Rotary WS. RIH w/cement bailer. Dumped 2 sks. cement on bridge plug @ 4140'. RD WL.

01/20/98 RIH w/5-1/2" Baker CIBP & set @ 4090'. Circulated pkr. fluid. POH & LD tbg. Well is TA'd.

09/10/01 Tested casing to 500 psi for 30 minutes with a pressure drop of not greater than 10%.

This Approval of Temporary
Abandonment Expires 9/26/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE September 10, 2001
TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

5
C
R