

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.		5a. Indicate Type of Lease State ☒ Fee ☐ 5. State Oil & Gas Lease No. E-2439
1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Water Injection Well 2. Name of Operator Murphy H. Baxter 3. Address of Operator P. O. Box 2040 Midland, Texas 79702 4. Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 1 TOWNSHIP 18S RANGE 33E N.M.P.M.	7. Unit Apparent Name N. EK Queen Unit 8. Farm or Lease Name Tract 2 9. Well No. 3 10. Field and Pool, or Wildcat EK Yates 7 Rivers Queen	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER _____	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

***Commission will be notified 24 hrs. prior to commencing work.**

1. Trip in hole with CIBP. Set CIBP @ 3950'.
2. Spot 35' of cement on top of CIBP.
3. Displace hole with mud-laden fluid. Close pipe rams. Test plug and casing to 500#'s.
4. Perforate 4 holes @ 1600'. (Top of anhydrite @ 1630'.) Circulate or squeeze 50 sks. or sufficient cement to isolate anhydrite section. WOC.
5. Tag plug in casing. Test to 500#'s.
6. Spot cement plug 50' above and below surface casing shoe @ 1650'. WOC.
7. Tag and test plug to 500#'s. Cut bradenhead and weld steel plate on casing. Set P & A marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Chuck Sledge **Chuck Sledge** TITLE Petroleum Engineer DATE 8-13-87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 25 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 24 1981
OCCO
HOBBS OFFICE