Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

o Appropriate District Office	Liter 6), removals and re		societes Department			Eca 1-1-89	
	OIL CONSERV	ATIO	N DIVISION				
O. Box 1980, Hobbs NM 88241-1980	Box 1980, Hobbs NM 88241-1980 2040 Pacheco St.				WELL API NO. 3002501966		
STRICT II D. Drawer DD, Ariesia, NM 88210 Santa Fc, NM 87505				5. Indicate Type of	Lease STATE X	FEE	
ISTRICT III 000 Rio Brazos Rd., Aziec, NM 87410				6. State Oil & Gas L		120	
				E-1774 - 2			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							
DIFFERENT RESER	POSALS TO DRILL OR TO U RVOIR. USE "APPLICATION F -101) FOR SUCH PROPOSAL	OH PEHN	MIT"	7. Lease Name or U	nit Agreement	Name	
Type of Well: OIL GAS WELL WELL WELL				Bridges Sta	te		
				8. Well No.			
Name of Operator Mack Energy Corp	oration			1			
Address of Operator				9. Pool name or Wildcat			
P.O. Box 960, Ar	tesia, NM 88211			Vacuum: Grb	g. SA		
Well Location Unit Letter N: 660	Feet From The So	uth	Line and1	980 Feet From	The Wes	st Line	
· · · · · · · · · · · · · · · · · · ·				T.a.a			
Section 3	Township 17S		nge 34E er DF, RKB, RT, GR, et	TATATE IAT	?//////////	County	
	////// IU. Elevation (Sad	ум мисте	I DI, KKD, KI, GK, C	·-,			
Charle Ar	propriate Box to Inc	dicate	Nature of Notice.	Report, or Ot	her Data		
	NTENTION TO:	uicate	SUE	SEQUENT	REPORT	OF:	
NOTICE OF II	TENTION TO.						
RFORM REMEDIAL WORK	PLUG AND ABANDON	X	REMEDIAL WORK	A	LTERING CA	SING.	
MPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	a OPNS. P	LUG AND AB	ANDONMENT L	
LL OR ALTER CASING			CASING TEST AND CI	EMENT JOB			
HER:			OTHER:				
2. Describe Proposed or Completed Op	erations (Clearly state all ner	tinent det	ails, and give pertinent de	ites, including estimat	ed date of star	rting any proposed	
work) SEE RULE 1103.	ciadolis (Cicari) scare an per	CHICAL CO.		SION MUST BE NO			
•			HOURS PRIO	R TO THE BEGIN	JIIILD 24 INING OF		
1. MIRU pluggin	g unit.		PLUGGING C	PERATIONS FOR	THE C-103		
2. Spot 25 sx c	mt. 4600-4500 ', WC	OC & t	ag. TO BE APPRO	VED.			
	le w/ 9.5# MLF.						
4. Spot 25 sx 2	570-2470'.		: 105	15001 NO			
5. Perforate 5-	1/2" csg. @ 1600',	, sqz	w/35 sx cmt. 16	000-T200, MOC	c tag.		
6. Perforate 5-	1/2" csg. @ 388',	sqz w	7/ 35 SX CMT. 30	30-200 , WUC 0	x Lag.		
7. Spot 10 sx 6	wellhead, install	dry h	ole marker. & o	lean location	n.		
o. KD, cut off	weilhead, install	ury n	ole markel, a				
Verbal Ap	proval From Gary V	Wink w	/ NM OCD on 5-	30-02			
I hereby certify that the information above	True and complete to the best of m	ny knowled					
SIGNATURE / UR	flulf	π	πε Superviso	r	DATE	05/31/02	
TYPE OR PRINT NAME TONY	Hall			————————————————————————————————————	TELEPHONE NO.	(505)748-128	
(This space for State Heat							
(This space for State Use)		SPECIA	g gere				

APPROVED BY_

CONDITIONS OF APPROVAL, IP ANY: