

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ANTA FE	
FILE	
J.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☒ Fee ☐	
5. State Oil & Gas Lease No. <u>B-1520</u>	
7. Unit Agreement Name	
8. Firm or Lease Name <u>Bridge Gate</u>	
9. Well No. <u>59</u>	
10. Field and Pool, or Wildcat <u>Vac (G-SA)</u>	
11. Elevation (Show whether DF, RT, GR, etc.) <u>4025 GR.</u>	
12. County <u>Lea</u>	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Mobil Oil Corporation

Address of Operator
Box 633, Midland, Texas 79701

Location of Well
UNIT LETTER L 660 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 13 TOWNSHIP 17S RANGE 34-E NMPM.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☒ CHANGE PLANS ☐ OTHER ☐
REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐ OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug & Abandon as per attached Procedure

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine O. Tucker TITLE Permit Clerk DATE 1-5-73

APPROVED BY Joe D. Ramey TITLE Dist. 1, Supv. DATE JAN 8 1973

CONDITIONS OF APPROVAL, IF ANY:

-- WELL WORK RECOMMENDATIONS
Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PE's, and Conversions

Lease: BRIDGES STATE Well No. 59
Field: VACUUM - SAN ANDRES FLOOD
County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE:

1. M.T.P.U. PULL TUBING (T.B.G. IS STUCK IN THE HOLE)
2. RUN 2" TUBING W/ CEMENT RETAINER. SET
RETAINER AT 4300' & SQUEEZE OPEN HOLE
3. CIRCULATE HOLE TO MUD LADEN FLUID.
4. DETERMINE FREE POINT OF 7" CASING. CUT OFF CASING
& PULL
5. SPOT 100' PLUG (355x), 50' ABOVE & 50' BELOW CUT
OFF POINT
IF CUT OFF POINT IS BELOW 1700', SET 100' PLUG
(355x) FROM 1700' TO 1800'
6. SPOT 100' CEMENT PLUG FROM 779' TO 879'
7. SPOT 105x CEMENT PLUG AT SURFACE.
8. CUT OFF WELL HEAD & INSTALL MARKER

BRIDGES STATE WELL N° - 59 -
 VACUUM - GRAYBURG SAN ANDRES
 LEA COUNTY - NEW MEXICO

CMT # / 250 - Sk -
 NMDC Form C-102 dated 3-30-40
 states 10 3/4' cemented to surface

10 3/4" Csg @ 829'

CMT # / 220 - Sk -

2 3/8" TBC @ 9'

7" Csg @ 4345'

T.D @ 4670'

AKH 4/1/72