NO. OF COPIES RECEIVED		Form C-103	
DISTRIBUTION	Supersedes Old C-102 and C-103		
SANTA FE			
FILE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65	
	+	Eq. Indiagram	
U.S.G.S.	1	State X Fee	
			
OPERATOR	J	5. State Cil & Gas Lease Nc.	
CHMICE	RY NOTICES AND REPORTS ON WELLS CROSALS TO CRILL OR TO DEEPEN OR FLUG BACK TO A DIFFERENT RESERVOIR.	mmmmmmm.	
JUNDA DO NOT USE THIS FORM FOR PRO USE "APPLICAT			
•	FION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name	
WELL WELL WELL	OTHER-		
mal.0 000	1 to	8. Form or Lease Name	
Address of Cyerator	9. Well No.		
Bay 633	80		
Location of Well	medland Julas 19701	10. Field and Pool, or Wildcat	
UNIT LETTER	660 FEET FROM THE MORTH LINE AND 1920 FEET	Vac. (J- JA)	
0		THITTINITY WORK	
THE fast LINE, SECTI	ON 13 TOWNSHIP 178 RANGE 34-E,	MMPM. (((((()))))	
mmmmm			
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
	4024 C.R.	Lieu IIIIII	
	Appropriate Box To Indicate Nature of Notice, Report o	r Other Data	
NOTICE OF IN	NTENTION TO: SUBSEQU	UENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	J . —	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT	
	OTHER	<u></u>	
OTHER			
7. Describe Proposed or Completed Co	perations (Clearly state all pertinent details, and give pertinent dates, incl		
work) SEE RULE 1103.	, , , , , , , , , , , , , , , , , , ,	name estimated date of starting any proposed	
	ing & abandon as for attached	, . 	
\mathcal{L}	e al les as Der attached	recommendation	
fli	ug & avandor as		
, ,			
8. I hereby certify that the information	above is true and complete to the best of my knowledge and belief.		
IGNED Mustine CO	Jucker Traction Clark	DATE 1-11-73	
7.0	THE THE	DATE / // /	
<u>a</u> D	De D. Ramey	JAN : 5 1077	
PRECYED AV	ist. I, Supv.	Court Sept 17	

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS Proposals for Well Reconditioning and Subsurfac Maintenance Workovers, Expense DD's, PB's, and Conversions

Lease:	Bridges State		Wel	1 No.	
Field:	Vacuum				
County:	Lea	State:	New Mexico		

RECOMMENDED PROCEDURE:

- 1. No tubing in hole. Run 2" tubing with cement retainer. Set retainer at 4615' and squeeze open hole.
- 2. Circulate hole to mud-laden fluid (mud should consist of 25 sx of gel per 100 bbls of water).
- 3. Cut and pull 5-1/2" casing (estimated recovery 350'). Set 100' cement plug (50' above & 50' below) cut off point (30sx).
- 4. Spot 10 sx of cement plug at surface.
- 5. Cut off wellhead and install marker.

NOTE: Verbally approved by NMOCC

ARA: RCL/cs 1/4/73 DIA GRAMMATIC WELL CHETCH L

BRI GEL STATE WELL N: 80

VACHUM - GRAVBURG SAU ANDRES

LEA COUNTY - NEW MEXICO

