

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	NAH
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	81993
7. Lease Name or Unit Agreement Name	New Mexico State "W"
8. Well No.	1
9. Pool name or Wildcat	Vacuum (Grayburg San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER Inj.	2. Name of Operator Questa Oil & Gas Co. Texaco Exploration & Production, Inc.
3. Address of Operator 7030 South Yale, Suite 700, Tulsa, OK 74136-5718	4. Well Location Unit Letter 0 : 660' Feet From The South Line and 1980 Feet From The East Line Section 13 Township 17-S Range 34-E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4010 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed start Date 9/25/93

- 1). Pull out of hole with equipment.
- 2). Set 5 1/2" CIBP at 4300' and Cap w/35' cement.
- 3). Load hole w/mud.
- 4). Spot 25 sacks of cement plug at 3190'.
- 5). Cut and Pull 5 1/2" Casing from approx. 2500'.
- 6). Spot 25 sacks of cement plug at 5 1/2" stub approx. 2500' + or - w.o.c. + Tag.
- 7). Spot 30 sacks of cement plug at 7 5/8" shoe @ 1655', 50' in + 50' out; w.o.c. + Tag.
- 8). Spot 10 sacks of cement at surface plug and set surface marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve Gray TITLE Agent for Texaco DATE 9/15/93
TYPE OR PRINT NAME Steve Gray E+P, INC. TELEPHONE NO. 806-894-6001

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE DEC 27 1993

CONDITIONS OF APPROVAL, IF ANY: