STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

THE THE PARTY OF T		
40. 07 COPIES SECEIVES	Ţ	
DISTRIBUTION		
SANTA FE	1	
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

CONDITIONS OF APPROVAL, IF ANYI

JIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-1-1	
FILE U.S.G.S.	4	5a. Indicate Type of Lease	
LAND OFFICE]	State X Fee	
OPERATOR	J	5. State Oil & Gas Lease No. B-1520	
SUNDE	RY NOTICES AND REPORTS ON WELLS	Milliam	
(DO NOT USE THIS FORM FOR PR	OPBALS TO DRILL OR TO SEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (ION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
1. OIL		7. Unit Agreement Name	
2. Name of Operator	OTHER-	0.5	
Mobil Producing TX. &	N.M. Inc.	8. Farm or Lease Name	
J. Address of Operator		Bridges State	
Nine Greenway Plaza,	Suite 2700, Houston, Texas 77046	34	
	60 South Line and 1980	10. Field and Pool, or Wildcat	
<u>}</u>			
West	14 17S 34E		
A THE THE PARTY OF			
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
16. Check	Appropriate Pow To Indiana Name (A)	Lea	
NOTICE OF I	Appropriate Box To Indicate Nature of Notice, Report	t or Uther Data EQUENT REPORT OF:	
		QUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	X ALTERING CASING	
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOS	PLUG AND ABANDONMENT	
	CHANGE PLANS CASING TEST AND CEMENT JQS	<u></u>	
OTHER			
17. Describe Proposed or Completed Op	perations (Clearly state all pertinent details, and give pertinent dates, i	including estimated date of starting any proposes	
-,,			
11/04-	HZ 4390-4705, Casing Record 10-3/4 @ 821, 7	@ 4390	
06/83 MIRU Permian WS Ut.			
11/07/83 Unseat pump, hot oiled rods & pump down tbg w/60 bbls lse oil, POH w/rods & pump, work 1 hr rel TAC, NU BOP, POH w/158 jts 2-7/8 8RT tbg & TAC, WIH w/2			
jts 2-7/8 tl	bg on SL, tag btm @ 4612/93' fill.	BRI the & IAC, WIH W/2	
11/08/83 WIH w/ 6-1/4 skirted Varel tooth type bit (SN 46968) 1 - 4-3/4 colon 2.7/9			
tby, tay on 111 @ 4455, circ W/150 bbls prod wtr. CO OH 4455-4705 circ			
hole clean 1 hr, pulled bit into csg @ 4255. 11/09/83 Ran bit to btm, tag btm @ 4705, no fill, POH w/ bit, WIH w/ 2 jts 2-7/8 tbg,			
/ baker k pkr, SN, Spot control valve on 2-7/8 tbg. set nkr @ 4355 end of TD			
@ 441/, RUT	idhu irucking to spotted 660 qals Uni-kem te	ch-clean 405 in SA OH7	
job campl @	own 2-7/8 tbg, closed spot valve, displ chem	w/ 25 bbls prod wtr,	
11/10/83 20 hr SITP (), rec spot valve w/ SL, sw 46 BLW/6 hrs, re	1 & POH w/nkr	
11/11-			
7000 psi, ta - SEE REVERSE	hydrojet tool w/2 - 3/16 jets, SN & 153 jt g btm @ 4702, pull tool to 4144.	s 2-7/8 tbg, HT in w/	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Dandala)	Authorized Agent	19/97/02	
BIGHED TIMEN W. U	TITLE	12/27/83	
ORIGINAL SIGNED BY J	ERRY SEXTON		
APPROVED BYDISTRICT I SUPE	KAIZOK	PAYE = AN / 1984	

#17. Continued from front.

11/14/83 WIH w/ HOWCO Hydrojet tool on 2-7/8 tbg, btm of tool @ 4702, drop spot control valve w/3000# spring, Hydrojetted SA OHZ 4702-4423 w/ 16,000 gals 15%DINE Fe HCl acid, treating press 7000-3000, AIR 2.5 BPM, holding 750 back press on csg while circ out csg tag btm @ 4612 = 90' fill, rev circ acid out w/ 250 bbls fresh wtr, job compl @ 6:30 pm, pulled tool to 4144.

11/15/83 Fin POH w/ hydrojet tool, WIH w/ 6-1/4 Varel RR tooth type bit, 1 - 4-3/4 col on 2-7/8 tbg, CO fill 4612-4705 TD, circ hole clean, POH w/ bit, LD 2-7/8 tbg.

11/16/83 WIH w/ 1 jt 2-7/8 OPMA, 2-7/8x4' perf tbg sub, SN, 10 jts 2-7/8 tbg, 7" Baker TAC, 138 jts 2-7/8 tbg, set btm of OPMA @ 4584, perf tbg sub @ 4539-4553, SN @ 4548, TAC @ 4240 w/ 10,000 T, ND BOP, NU Wellhead, ran 2-1/2x1-1/2x16 pump 1"x6' GA, 39 - 3/4, 77 - 7/8, 64 - 1" rods, 24' - 1" rod subs, 1-1/4x16 PR, HO well, rel Permian WS Ut, turned well to prod @ 3 PM, POP. RETURNED TO PRODUCTION.

RECTURRY

JAN 3 1984

Committee of the second

HOBBS OFFICE