

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02249
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-1080
7. Lease Name or Unit Agreement Name	VACUUM GRAYBURG SAN ANDRES UNIT
8. Well No.	41
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES

SUNDY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter F : 1980 Feet From The NORTH Line and 1980 Feet From The WEST Line
Section 1 Township 18S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4003' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ADDING PERFS & FRACTURING NEW PAY ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ADD PERFS & FRACTURE NEW PAY ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-16-99: MIRU.
4-19-99: C/O RAMS TO 2 3/8". TIH W/BIT & CSG SCRAPER ON 2 3/8" TBG TO 4439'.
4-20-99: TIH W/LOGGING TOOLS & ATTEMPT TO RUN CBL-UNSUCCESSFUL. TIH W/CIBP & SET @ 4435'. RU PUMP TRUCK. LOAD HLE W/175 BBLs 2% KCL WTR. ATTEMPT TO TEST CSG & CIBP. PUMP INTO CSG. TIH W/PKR, & SN ON TBG. PSA 4130'. TEST CIBP TO 500#-OK. LOCATE CSG LEAK 4161-4256'. TEST CSG 4161 TO SURF-500#-OK. PUMP INTO LEAK. PKR SET @ 4161'.
4-21-99: FL @ 200'. REL PKR & LOWER TO 4420'. RU PUMP TRUCK. CIRC HLE W/120 BBLs. TIH W/CAMERA & CHECK CSG 4161-4233'. HLES IN CSG. TIH W/CMT RET TO 4068'.
4-22-99: PUMP THRU RET W/20 BFW. SET RET @ 4068'. TEST TBG TO 2500#-OK. PRESS CSG TO 500#-OK. MIX 100 SX CL C. STING OUT OF RET. REV OUT.
4-23-99: TIH W/BIT, DC'S & TBG. TAG CMT @ 4067'. DRILL 1' CMT ON RET @ 4066'. DRILL RET @ 4066' & CMT TO 4130'.
4-24-99: DRILL 115' CMT TO 4255'. FELL OUT CMT. TEST SQZ TO 300 PSI-OK. TIH TO 4430'. CIRC W/2% KCL.
4-26-99: TIH W/LOG TOOL. RUN CBL/GR/CNL LOG FR 4435-3435'. TIH W/HEG GUN, PERF 4304-4424'. TIH W/PKR, SN, & TBG. TEST TBG TO 5000 PSI. PSA 4264'. LOAD & PSI CSG TO 300-OK.
4-27-99: PSI CSG TO 300 PSI-OK. ACIDIZE 4304-4424' W/4000 GALS 15% HCL NEFE ACID. RU SWAB. FL @ 2000'. END FL @ 2800'.
4-28-99: REL PKT. TIH W/BIT, DC'S & TBG. TAG @ 4432'. PUMP 260 BFW. NO CIRC. PULL BIT TO 4100'.
4-29-99: TIH W/BIT TO 4432'. PUMP 280 BBLs WTR. TIH W/BIT & BAILER ON TBG. TAG @ 4432'. C/O 4' FILL. DRILL ON CIBP @ 4436-4437'.
4-30-99: LOWER BIT TO 4437'. DRILL CIBP LOOSET & CHASE TO 4541'. DRILL 6" ON PLUG.
5-01-99: TIH W/MOTOR, GAS SEPR, PMP, & TBH. MOTOR @ 4258'. NDBOP. NUWH. WELL PUMPED UP @ 1:15 PM. RIG DOWN.
5-10-99: ON 24 HR OPT. PUMPED 21 BO, 128 BW, & 27 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 5/19/99
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: