DeSoto Nichols 12-93 ver 1.0

Energ_.

is and Natural Resources Department

DISTRICT I	OH	COMORDA		ON DIMICION		Revis	sed 1-1-69	
P.O. Box 1980, Hobbs, NM 8	8240 OIL			ON DIVISION	WELL API NO	D.		
DISTRICT II					30-025-02271			
P.O. Box Drawer DD, Artesia, NM 88210 DISTRICT III Santa Fe, New Mexico 87504-2088					5. Indicate	Type of Lease STATE 🖸	FEE 🗌	
1000 Rio Brazos Rd., Aztec, NM 87410					6. State Oil / Gas Lease No. B-1189			
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						7. Lease Name or Unit Agreement Name VACUUM GRAYBURG SAN ANDRES UT		
1. Type of Well: OIL WELL	GAS WELL	OTHER						
Name of Operator TEXACO EXPLORATION & PRODUCTION INC.						8. Well No. 24		
3. Address of Operator 205 E. Bender, HOBBS, NM 88240						9. Pool Name or Wildcat VACUUM GRAYBURG SAN ANDRES		
4. Well Location						OUM GRATBURG SAN ANDE	165	
Unit Letter 1 : 1980 Feet From The SOUTH Line and 660 Feet From The EAST Line								
BHL= J. 19716 454 1772 FEL Township 18S Range 34E NMPM LEA COUNTY								
, ,	10. Ele	evation (Show whethe	er DF, RK	(B, RT,GR, etc.) 4002' GR				
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data								
						JBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	☐ PLUG AI	ND ABANDON		REMEDIAL WORK	⊠	ALTERING CASING		
TEMPORARILY ABANDON	CHANGE	PLANS		COMMENCE DRILLING OPE	RATION	PLUG AND ABANDONMEN		
PULL OR ALTER CASING				CASING TEST AND CEMEN	T JOB			
OTHER:			_ 🗆	OTHER:	H	prizontal		
9/14/99: MIRU KEY SERVICE UNIT. TOH & LD PMP, RDS & TBG. 9/15/99: PUMP 100 BFW DN CSG. WELL ON VAC. 9/16/99: FILL RESERVE PIT & RU DE-GASSER ON FLOWLINE. UNLOAD DP ON RACKS. 9/17/99: TIH W/DP. TIH W/HOOK TO TOP OF FISH. LATCH INTO TOP OF WHIPSTOCK. TIH W/SPEAR, BMPR SUB, JARS & DC'S. SPEAR FISH. HIT JARS 1 TIME & PKR CAME LOOSE. LD PKR & MANDREL. RECVD ALL OF FSH. PI BIT & CSG SCRAPER & TIH W/STANDS FROM DERRICK. 9/18/99: TRY TO LOAD HLE. PUMP 400 BFW. UNABLE TO FILL. FILL UP KR ASSEMBLY & WHIPSTOCK WWTR. TIH W/FKRWHIPSTOCK ASSY. TIH W/GYRO. RUN KEEPER SURVEY FR SURF TO 4220'. ORIENT WHIPSTOCK. RIG DOWN. SET SLIPS. LOAD DP W/WTR. WKK DP STRING TO SHEAR OFF WHIPSTOCK. TIH W/STARTER MILL. 9/19/99: MILL ABOVE WHIPSTOCK FR 4221-4230. MILL FR 4230-4240. TOH W/MILLS. PU BHA #1 & TIH TO BTM OF WHIPSTOCK @ 4230. SLIDE DRILL FR 4230-4233, 4233-4234, 4234-4254, 4254-4271. 9/20/99: SLIDE DRILL FR 4523-4533. ROTARY DRILL FR 4563- 4664, 4674, 4759, 4784, 4790, 4815, 4822, 4879, 4886, 4906, 4917, 4932, 4948, 4958, 5043, 5100, 512 9/22/99: SLIDE DRILL FR 5130-5163, 5170, 5195, 5201, 5226, 5233, 5225, 5331, 5390, 5400, 5453, 5463, 5570. TD HLE AT MIDNIGHT. PUMP 65 BBLS 10 PPG BRINE. FLOWING. PULL DP TO 4012'. CIRC 65 BBLS OF 10 PPG BRINE. 9/23/99: OPEN WELL & FLOW BACK TO RESERVE. 9/24/99: START PUMPING 10 PPG BRINE. PUMP 150 BBLS & SHUT DOWN. OPEN WELL & FLOW DN. OPEN OFFET INJECTO. RS & FLOW BACK. 9/25/99: BLEED 150 PSI OFF DP & 120 PSI OFF CSG. PU SHORT CATCH OVERSHOT W/GRAPPLE, DRAIN SUB, BMPR SUBS, JARS & DC'S. 9/25/99: BLEED 150 PSI OFF DP & 120 PSI OFF CSG. PU SHORT CATCH OVERSHOT W/GRAPPLE, DRAIN SUB, BMPR SUBS, JARS & DC'S. 9/26/99: BLEED 150 PSI OFF DP & 120 PSI OFF CSG. PU SHORT CATCH OVERSHOT W/GRAPPLE, DRAIN SUB, BMPR SUBS, JARS & DC'S. 9/26/99: BLEED 150 PSI OFF DP & 120 PSI OFF CSG. PU SHORT CATCH OVERSHOT W/GRAPPLE, DRAIN SUB, BMPR SUBS, JARS & DC'S. 9/26/99: BLEED 150 PSI OFF DP & 120 PSI OFF CSG. PU SHORT CATCH OVERSHOT W/GRAPPLE, DRAIN SUB, BMPR SUBS, JARS & DC'S. 9/26/99: BLEED 150 PSI OFF DP & 120 PSI OFF								
I hereby certify that the information above is true		of my knowledge and belief.						
SIGNATURE CANAL	ise ya	TITLE_	Liigin	eering Assistant	<u>. – </u>	DATE11/22/1999)	
TYPE OR PRINT NAME	J. Denise	Leake				Telephone No. 397-040	05 	
(This space for State Use)								
APPROVED BY	ANV.	TITLE				DATE		
CONDITIONS OF APPROVAL, IF A	NY:							