

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-1189

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" FORM (O-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

TEXACO Inc.
Address of Operator

P.O. Box 728, Hobbs, NM 88240

Location of Well

UNIT LETTER **J**, **1980** FEET FROM THE **South** LINE AND **1980** FEET FROM

THE **East** LINE, SECTION **2** TOWNSHIP **18-S** RANGE **34-E** N.M.P.M.

11. Elevation (Show whether DF, RT, GR, etc.)

4017' (DF)

12. County

Lea

7. Unit Agreement Name

Vacuum Grayburg San Andres Unit

8. Field, Pool, or Unit Name

Vacuum Grayburg San Andres Unit

9. Well No.

23

10. Field and Pool, or Unit Name

Vacuum Grayburg San Andres

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER **Repair Water Flow** ☒

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull production equipment. Install BOP.
2. Set RBF @ 3000' & dump 10' sand on plug.
3. Perforate 5-1/2" casing w/2 JS @ 1669'.
4. Set cement retainer @ 1600' & establish circulation. Cement w/500 sx. Class "H" cement containing 2% CaCl. Squeeze w/250 sx. Class "H" cement containing 2% CaCl. Circulate cement, if possible. WOC. DOC & test. Run temperature survey if cement does not circulate.
5. Pull RBF. Set pkr @ 3950'. Acidize open hole section 4206-4710' w/3000 gal. 15% NE FE Acid.
6. Install production equipment. Test & return to production.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

[Signature]

TITLE **Asst. Dist. Supt.**

DATE **11-11-80**

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: