

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. B-1189
7. Unit Agreement Name Vacuum Grayburg San Andres Unit
8. Farm or Lease Name Vacuum Grayburg San Andres Unit
9. Well No. 7
10. Field and Pool, or Wharft Vacuum Grayburg San Andres
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER ☐
Name of Operator TEXACO Inc.		
Address of Operator Drawer 728, Hobbs, New Mexico 88240		
Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1987 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 18-S RANGE 34-E NEPM		

15. Elevation (Show whether DF, RT, GR, etc.)
4013' (DF)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Repair Water Flow and Treat	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull production equipment. Install BOP.
2. Set RBP at 3000' and dump 10' sand on plug.
3. Perforate 5-1/2" csg w/2-JS at 1675'.
4. Set cement retainer at 1600'. Cement w/530 sx. Class "H" cement containing 2% CaCL. Squeeze w/additional 250 sx. Class "H" cement containing 20% CaCL. Circulate to cement or run Temperature Survey. WOC. DOC. Test.
5. Clean out to 4710'. Set packer at 4000'.
6. Acidize open-hole section 4311-4710' with 2500 gals. 15% NEFE acid.
7. Run production equipment. Test and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. L. Smith TITLE Ass't. Dist. Supt. DATE 11-24-80

APPROVED BY Dist. Supt. TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: