

OIL CONSERVATION DIVISION

P. O. BOX 1088

SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
ALBUQUERQUE	
UTAH	
LAND OFFICE	
OPERATOR	

a. Indicate Type of Lease State ☒ For ☐
b. State Oil & Gas Lease No. 8-1446
c. Unit Agreement Name West Vacuum Unit
d. Field or Lease Name West Vacuum Unit
e. Well No. 45
f. Field and Loc. or Well Unit Vacuum Grayburg San Andres
g. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR RE-DRILL OR TO A DIFFERENT RESERVOIR.
(SEE APPLICATION FOR PERMIT TO DRILL AND CASE FOR SUCH PROPOSALS)

1. OIL ☒ GAS ☐ OTHER ☐

2. Name of Operator
TEXACO Inc.

3. Address of Operator
P.O. Box 728, Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER E 500 FEET FROM THE North 1000 FEET FROM
THE East LINE, SECTION 3 TOWNSHIP 18S RANGE 34E

15. Elevation (Show whether BF, BT, GR, etc.)
4026' (GR)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

COMMENCE DRILLING OPS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods, tubing & pump.
2. Set pkr @ 4138'. Acidize open-hole 4109-4775' w/3000 gals gelled acid in 3 stages using 2400# rock salt between stages. Flushed w/100 bbls. salt water.
3. Install pumping equipment. Test and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]

TITLE Asst. District Supt.

DATE 11-15-79

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF Dist. 1, Supt.

TITLE

DATE NOV 20 1979