Submit 3 Copies To Appropriate District	Ctota of Norman	••-	
Office	State of New Mexico		Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u>	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-02288 5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE X FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No. 858150
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Samuel Palito.
PROPOSALS.)			West Vacuum Unit
Type of Well: Oil Well XX Gas Well Other			
2. Name of Operator			8. Well No.
Chevron Texaco Corporation			8. Well No.
3. Address of Operator			9. Pool name or Wildcat
P.O. Box 3109 Midland, Texas 79702 4. Well Location			Vacuum Grayburg San Andres Unit
4. Well Excation			
Unit Letter D: 330 feet from the North line and 330 feet from the West line			
Continue A			
Section 4	Township 18S	Range 34E	NMPM Lea County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SURS			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PL	UG AND ABANDON 🔲	REMEDIAL WORK	
TEMPORARILY ABANDON CH	HANGE PLANS	COMMENCE DRIL	_
PULL OR ALTER CASING MULTIPLE CASING TEST AND			ABANDONMENT
	MPLETION	CEMENT JOB	
OTHER:		OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of			
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.			
1. RIH Tag CIBP @ 4415 spot 25 sxs. Plug 4415 to 4215 (Grayburg-San Andres) Tag @ 4163			
2. Displace hole w/MLF, 9.5# Brine w.25# gel P/BBL			
3. Perf 6 holes @ 3800 unable to sqz. spot 40 sxs. Plug 3850 to 3600 (Queen) Tag @ 3512 4. Perf 6 holes @ 2800 unable to sqz. spot 40 sxs. Plug 3850 to 3600 (Vetes P. S. IV. T			
4. Perf 6 holes @ 2800 unable to sqz. spot 40 sxs. Plug 3850 to 2600 (Yates, B-Salt) Tag @ 2484			
5. Perf 6 holes @ 1800 sqz. perf w/ 125 sxs. 1800 to 1500 (8 5/8 shoe T-Salt) Tag @ 1418			
110 Ko Horo			
6. CIRC cmt. 30 to surf. w/15 sxs., install dry hole marker 2/14/02			
\$\$ 05 62 \$\frac{1}{10}\$			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE ()		MANAGER	DATE 2/14/02
Type or print name Jimmy BAG	KEY		Telephone No. 9/5-683-4996
(This space for State use)			
APPPROVED BY Solumba TITLE COMPLIANCE OFFICER DATE			
Conditions of approval, it ally:			
GWW			