

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.

30-025-02288

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

858150

7. Lease Name or Unit Agreement Name:

West Vacuum Unit

8. Well No.

39

9. Pool name or Wildcat Vacuum,  
Grayburg, San Andres Unit

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Texaco Exploration & Production, Inc.

3. Address of Operator

P. O. Box 3109, Midland, TX 79702

4. Well Location

Unit Letter D : 330 feet from the North line and 330 feet from the West line

Section 4

Township 18S Range 34E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. RIH Tag CIBP @ 4415', Spot 25 Sx plug 4415'-4215' (Grayburg-San Andres) WOC Tag.
2. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL.
3. Perf 6 holes @ 3800', Sqz 50 Sx plug 3800'-3600' (Queen)
4. Perf 6 holes @ 2800', Sqz 50 Sx plug 2800'-2600' (yates, B-Salt) WOC Tag
5. Perf 6 holes @ 1800', Sqz 125 Sx plug 1800'-1500' (8 5/8" shoe, T-Salt) WOC Tag.
6. 10 Sx Surface, Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James T. Corbitt TITLE FACILITY ENGR

DATE 11/5/01

Type or print name JAMES T. CORBITT

Telephone No. 688-4438

(This space for State use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

Conditions of approval, if any:

ONCE APPROVED BY  
CARRY OVER TO  
NATURAL SOURCE MANAGER - 2

DATE NOV 19 2001