

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-02290
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Injection <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Chevron USA, Inc.		6. State Oil & Gas Lease No. B-3936
3. Address of Operator 15 Smith Rd. Midland, Tx 79705		7. Lease Name or Unit Agreement Name: West Vacuum Unit
4. Well Location Unit Letter <u>C</u> : <u>660</u> feet from the <u>north</u> line and <u>1980</u> feet from the <u>west</u> line Section <u>4</u> Township <u>18-S</u> Range <u>34-E</u> NMPM County <u>Lea</u>		8. Well No. 40
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Vacuum Grayburg S.A.

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

- 12. Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
1. Set 5 1/2 CIBP @ 4350 spot 25sx plug fr/4350-4150(Grayburg-San Andres)tag @ 4133
 2. Displace hole w/MLF 9.5# Brine w/25# Gel P/BBL.
 3. Spot 25sx plug fr/2700-2500(Yates,B-salt)Tag @ 2480
 4. Spot 25sx plug fr/1600-1400(8 5/8 shoe,T-salt)Tag @ 1365
 5. Spot 40sx plug fr/300-surf(surf)Tag @ surf
 6. Install dry hole marker 1-30-03

Approved as to plugging of the Well Bore.
Liability of the well is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER/SUNSET DATE 1-30-03

Type or print name JIMMY BAGLEY
(This space for State use)

Telephone No. 915 520-8756

APPROVED BY _____
Conditions of approval, if any:

ORIGINAL SIGNED BY
GARY W. TWINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

FEB 11 2003
DATE