

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State ☒ Fee ☐
5. State Oil & Gas Lease No.	B4118

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL OR TO RE-OPEN OR PLUG BACK FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
Murphy H. Baxter

3. Address of Operator
P. O. Box 2040 Midland, Texas 79702

4. Location of Well
UNIT LETTER E 1980 FEET FROM THE North LINE AND 330 FEET FROM
West LINE, SECTION 6 TOWNSHIP 18S RANGE 34E N.M.P.M.

7. Unit Agreement Name
N. EK Queen Unit

8. Farm or Lease Name
Tract 3

9. Well No.
2

10. Field and Pool, or Wildcat
EK Yates 7 Rivers Queen

12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
4091 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*Commission will be notified 24 hrs. prior to commencing work.

1. Trip in hole with CIBP. Set CIBP . @ 4075'.
2. Spot 35' of cement on top of CIBP.
3. Displace hole with mud-laden fluid. Close pipe rams. Test plug and casing to 500#'s.
4. Perforate 4 holes @ 1600'. (Top of anhydrite @ 1640'.) Circulate or squeeze 50 sks. or sufficient cement to isolate anhydrite section. WOC.
5. Tag and test plug to 500#'s.
6. Spot cement plug 50' above and below surface casing shoe @ 318'. WOC.
7. Tag and test plug to 500#'s. Cut bradenhead and weld steel plate on casing. Set P & A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CHUCK SLEDGE Chuck Sledge TITLE Petroleum Engineer DATE 8-13-87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

AUG 25 1987

RECEIVED
AUG 24 1987
OCD
HOBS OFFICE