

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐ 5. State Oil & Gas Lease No. E-8714
1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER- Temporarily Abandoned 2. Name of Operator Murphy H. Baxter 3. Address of Operator P. O. Box 2040 Midland, Texas 79702 4. Location of Well UNIT LETTER B 330 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 18S RANGE 34E NMPL. 15. Elevation (Show whether DF, RT, GR, etc.) 4093 GR		7. Unit Agreement Name N. EK Queen Unit 8. Farm or Lease Name Tract 4 9. Well No. 5 10. Field and Pool, or Wildcat EK Yates 7 Rivers Que 12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ PULL OR ALTER CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐		SUBSEQUENT REPORT OF:
---	--	------------------------------

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*Commission will be notified 24 hrs. prior to commencing work.

1. CIBP has been set @ 4100'. (6-1-82)
2. Spot 35' of cement on top of CIBP .
3. Displace hole with mud-laden fluid. Close pipe rams. Test plug and casing to 500#'s.
4. Perforate 4 holes @ 1690'. (Top of anhydrite @ 1720'.) Circulate or squeeze 50 sks. or sufficient cement to isolate anhydrite section. WOC.
5. Tag and test to 500#'s.
6. Spot cement 50' above and below surface casing shoe @ 329'. WOC
7. Tag plug. Cut off bradenhead and weld steel plate on casing. Set P & A marker.

10 sack surface plug

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <i>Chuck Sledge</i> Chuck Sledge	TITLE Petroleum Engineer	DATE 8-13-87
APPROVED BY Paul Rantz Geologist	TITLE	DATE AUG 24 1987
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
AUG 24 1927
QCD
MCBRS OFFICE