

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

JAN 24 11 52 AM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
Unknown

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name - |
| 2. Name of Operator Sunray DX Oil Company | 8. Farm or Lease Name New Mexico "H" State |
| 3. Address of Operator P. O. Box 1416, Roswell, New Mexico | 9. Well No. 2 |
| 4. Location of Well UNIT LETTER M 660 FEET FROM THE West LINE AND 660 FEET FROM THE South LINE, SECTION 8 TOWNSHIP 18S RANGE 34E NMPM. | 10. Field and Pool, or Wildcat E. K. Queen |
| 15. Elevation (Show whether DF, RT, GR, etc.) 4072 G.L. | 12. County Lea |



Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|---|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Loaded hole w/mud.
2. Placed 25 sx cmt plug over perfs 4404-4300'.
3. Cut off 5 1/2" csg @ 1640'. Pulled csg.
4. Placed 25 sx cmt plug 2010-1910 and 25 sx cmt. plug 1650-1550 (in and out of 5 1/2" stub).
5. Placed 25 sx cmt plug 245-145 in base of surface pipe.
6. Placed 10 sx cmt plug at surface and installed dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| | | | |
|---|---------------------|--------------------------------|---------------------|
| SIGNED  | B.F. Brawley | TITLE District Engineer | DATE 1-23-67 |
| APPROVED BY  | | TITLE | DATE |
| CONDITIONS OF APPROVAL, IF ANY: | | | |